



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388

*Atul Steve
Final Bill*

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Ms Chan Yin Ha 3 Pandan Valley #11-302A Singapore 597627 Mobile: 96196856		
			Document No. 0				
			Document Date 05/10/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0	20062	64DS/SLK9288C/260821
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	13/09/2021 8.00		21/09/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS.:INDIA ACC DATE:26.08.2021 T/P VEHICLE NO.:SLV9667J DATE-IN:13.09.2021 DATE SURVEY:01.09.2021 NO OF REPAIR DAYS:6 DAYS YOUR REF:CC4/GRB21009034/ bs3BY:STEVE (LKK) *DIRECT SETTLEMENT*				50.00	
2	B	BP-LAB3 TRANSFER R/F AND R/R DOORS COMPONENT AND MECHANISM TO NEW DOOR SHELLS. (NETT)	*			1732.00	
3	B	BP-LAB3 REMOVE/REFIX RHS ROCKER MLDG. (NETT)	*			433.00	
4	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR CENTRE PILLAR, RHS ROCKER PANEL AND FIT NEW PARTS.	*			1299.00	
5	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			2226.00	
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00	
7	S	BP-SUBLET TO RESET ECU & REPROGRAMME. (NETT)	0742			216.50	
8	1	L67863-53030 WEATHERSTRIP, FR	1.00	62.30		62.30	
9	2	L90269-04051 RIVET	14.00	1.50		21.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388




ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Ms Chan Yin Ha 3 Pandan Valley #11-302A Singapore 597627 Mobile: 96196856
	Document No. 0	
	Document Date 05/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0	20062	64DS/SLK9288C/260821
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHBA1D2805032851	8ARZ047787	60	Wally Tan G H	13/09/2021	8.00	21/09/2021	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	3	L76923-52021 RETAINER, SIDE	6.00	6.60		39.60
11	4	L76921-53020 PROTECTOR, SIDE	1.00	21.10		21.10
12	5	L76921-53010 PROTECTOR, SIDE	2.00	21.10		42.20
13	6	L75968-53010 TAPE, BLACK OUT FR	1.00	38.40		38.40
14	7	L75951-53010 TAPE, BLACK OUT FR RH	1.00	38.40		38.40
15	8	L75937-53010 TAPE, BLACK OUT RR RH	1.00	65.90		65.90
16	9	L75929-53010 TAPE, BLACK OUT FR RH	1.00	69.90		69.90
17	0	L75867-33030 TRIM BOARD CLIPS,	11.00	11.00		121.00
18	1	L75867-30120 CLIP	1.00	11.00		11.00
19	2	L75864-50020 PROTECTOR, ROCKER	4.00	11.60		46.40
20	3	L75862-53070 PROTECTOR, ROCKER	1.00	26.90		26.90
21	4	L75862-53060 PROTECTOR, ROCKER	1.00	47.90		47.90
22	5	L75761-53020 MOULDING, RR DOOR	1.00	71.40		71.40
23	6	L75755-53020 MOULDING, RR DOOR LH	1.00	75.40		75.40
24	7	L67857-53020 PROTECTOR, RR DR RH	1.00	55.60		55.60
25	8	L67003-53070 PANEL, DOOR RR RH	1.00	1138.70		1138.70
26	9	L67001-53120 PANEL, DOOR FR RH	1.00	1361.30		1361.30
27	0	L58741-53030 PROTECTOR, QUARTER RH	1.00	29.00		29.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle		9,539.90
		Parts 3,383.40	GST 7.00% 667.79
		Labour 5,940.00	
		Sublet 216.50	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 10,207.69

Customer Copy