



Borneo Motors



Inchcape

Co. Reg No. : 1987000862
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no : 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chan Yin Ha		
			Document No.		3 Pandan Valley		
			0		#11-302A		
			Document Date		Singapore 597627		
			27/08/2021		Mobile: 96196856		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0	20062	64TP/SLK9288C/260821
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBA1D2805032851	8ARZ047787	60	Wally Tan G H	--/--/----		0.00	--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	80.00
2	B	BP-LAB3 TRANSFER R/F AND R/R DOORS COMPONENT AND MECHANISM TO NEW DOOR SHELLS. (NETT)	866 x 2				1732.00
3	B	BP-LAB3 REMOVE/REFIX RHS ROCKER MLDG. (NETT)					433.00
4	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR CENTRE PILLAR, RHS ROCKER PANEL AND FIT NEW PARTS.	866 x 1-5			1299	2598.00
5	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	3 x 742			2226	2597.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)	170 x 2				200.00
7	S	BP-SUBLET TO RESET ECU & REPROGRAMME. (NETT)					216.50
8	1	L67001-53120 PANEL, DOOR FR RH	1.00	1361.30			1361.30
9	2	L75929-53010 TAPE, BLACK OUT FR RH	1.00	69.90			69.90
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Chan Yin Ha				
		Document No. 0	3 Pandan Valley #11-302A Singapore 597627				
		Document Date 27/08/2021	Mobile: 96196856				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0	20062	64TP/SLK9288C/260821
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	3	L75968-53010 TAPE, BLACK OUT FR <i>REC</i>	1.00	38.40		38.40 ✓	
11	4	L67863-53030 WEATHERSTRIP, FR <i>REC</i>	1.00	62.30		62.30 ✓	
12	5	L75755-53020 MOULDING, RR DOOR RH <i>REC</i>	1.00	75.40		75.40 ✓	
13	6	T68710-12151 R/FRT UPP DOOR HINGE, <i>X n n</i>	1.00	98.20		98.20 ✓	
14	7	T68730-12120 R/FRT DOOR LOW HINGE, <i>X n n</i>	1.00	112.00		112.00 ✓	
15	8	L67003-53070 PANEL SUB-ASSY, RR <i>09</i>	1.00	1138.70		1138.70 ✓	
16	9	L75951-53010 TAPE, BLACK OUT RR <i>REC</i>	1.00	38.40		38.40 ✓	
17	0	L75937-53010 TAPE, BLACK OUT RR <i>REC</i>	1.00	65.90		65.90 ✓	
18	1	L67857-53020 L/R EAR DOOR PROTECTOR, <i>REC</i>	1.00	55.60		55.60 ✓	
19	2	L75761-53020 MOULDING, RR DOOR <i>REC</i>	1.00	71.40		71.40 ✓	
20	3	L90269-04051 RIVET <i>REC</i>	14.00	1.50		21.00 ✓	
21	4	T68750-20122 HINGE ASSY, RR DOOR, <i>X n n</i>	1.00	99.60		99.60 ✓	
22	5	T68770-52031 R/RR LOW DOOR HINGE, <i>X n n</i>	1.00	87.90		87.90 ✓	
23	6	L58741-53030 PROTECTOR, QUARTER RH <i>REC</i>	1.00	29.00		29.00 ✓	
24	7	L75862-53060 PROTECTOR, ROCKER <i>REC</i>	1.00	47.90		47.90 ✓	
25	8	L75862-53070 PROTECTOR, ROCKER <i>REC</i>	1.00	26.90		26.90 ✓	
26	9	L76921-53010 PROTECTOR, SIDE <i>REC</i>	2.00	21.10		42.20 ✓	
27	0	L76921-53020 PROTECTOR, SIDE <i>REC</i>	1.00	21.10		21.10 ✓	
28	1	L75864-50020 PROTECTOR, ROCKER <i>REC</i>	4.00	11.60		46.40 ✓	
29	2	L75867-33030 CLIP, ROCKER PANEL <i>REC</i>	11.00	11.00		121.00 ✓	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet		Amount Due		
			Lubrication/Fluid				
			Others				

Customer Copy

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 Pandan Crescent
 Singapore 128462, Tel no. 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chan Yin Ha 3 Pandan Valley #11-302A Singapore 597627 Mobile: 96196856			
			Document No.					
			0					
			Document Date					
			27/08/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASE30R	AEZLQ S1	28/11/2016	SLK9288C	0	20062	64TP/SLK9288C/260821	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	3	L76923-52021 RETAINER, SIDE			6.00	6.60		39.60
31	4	L75867-30120 CLIP			1.00	11.00		11.00
Stevr (LKK) 1/9/21, 10.00am WKL PL 6 dys P/P My Bel sy								
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							11,637.60	
Date:			Please acknowledge receipt of vehicle		Parts		GST 7.00%	
					Labour		814.63	
					Sublet		Less	
					Lubrication/Fluid		0.00	
					Others		0.00	
					Amount Due		12,452.23	

Customer Copy