# GARAGE 13 PTE LTD

8 KAKI BUKIT AVE 4 #03-46 PREMIER@KB SINGAPORE 415875 TEL: 9666 4445

24<sup>TH</sup> AUG 2021

Our Ref: FBP8999H Your Ref: SLP9053L

MSIG INSURANCE PTE LTD Motor Claims Department 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581

Dear Sirs,

### ACCIDENT INVOLVING FBP899H AND SLP9053L ALONG BEDOK NORTH AVE 3 TWS PIE ON 15.10.2020

We are the representative for MUHAMMAD TAJUDDIN BIN ISMAIL, whose vehicle registration number **FBP8999H** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration SLP9053L. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

	\$	6,418.45
LTA search fee	\$\$	7.45
Survey report	\$	482.00
Towing	\$	100.00
Loss of USE for 16 days @\$50 /day	\$	800.00
Cost of repairs	\$	5,029.00

Enclosed are the supporting documents for your perusal:-GIA LTA search

Kindly let us have your payment of \$6,418.45 in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Irene at 6385 1171 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Repair bill

Encl.

# **GARAGE 13**

8 Kaki Bukit Ave 4 Premier @ Kaki Bukit #03-46 Singapore 415875

Company Reg Number: 202005684D

# **LETTER OF AUTHORISATION**

I/We, MUHAMMAD THATUDAN EN ISMAIL.	e third party claimant"
of NRIC/FIN/UEN No. 287079131 , owner of vehicle no. FBP 9999H	hereby authorize
M/s GADAGE 13 PTG UTD ("the workshop") to my c	laim for repair cost
and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. FBP 1990	that
was damaged pursuant to the accident which occurred on	along
BEDOK NORTH AVE 3 TOWARD PIE involving vehicle	no/s
("the accident").	
I further authorize the workshop to settle my above mentioned claim in a manner that they decords workshop is further authorized to receive payment further to settlement of my claim with payment made in favour of the workshop.  I further acknowledge that any settlement the workshop may reach on my behalf is on a without admission of liability basis insofar as the driver/ owner/ insurers of the other vehicle/s in the settlement that they decords in the settlement of my claim with payment made in favour of the workshop.	nent cheque/s being ut prejudice and
Dated this(day) of(month)(year)	
SIGNATURE OF OWNER/ COMPANY STAMP (IF APPLICABLE)	



# Kace Towing Specialists

Blk 120C Canberra Crescent #12-387 Singapore 753120

YK Mobile: 8866 6262

Email: kacetowingspecialists@gmail.com Business Reg. No.: 53399252D CASH SALE / JOB ORDER

# No. 8490

Junn Start/Changing of hattery	Tyre Replacement/Patching	Accident/Breakdown	Multi/Basement	With Load/Cargo Box	— King Dolly  Transport Charge	Low Body Kit	— Door Opening Service  Crane Up/Winch Out	Collect Doc/Key	Repo
Carh	年版 本型 AD899のリリ 年型 World, Forza	联络号码	It): Contact No:	1/ paind	To: G13 (2) Rest 187 Apriler	其他 Othere:			注意:本公司对所拖之车辆,在选行中如有任何损失或破坏,
Messrs:	车牌 Vehicle No. Z	时间(日/夜)	time (day/night):	cation:	1 613 To:	報额 loof	经手人 Authorised By:		主意: 本公司对自

E. & O. E.

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

一概由车主自行负责。

Woodlands and Tuas Checkpoint

# **GARAGE 13 PTE LTD**

8 KAKI BUKIT AVE 4 #03-46 PREMIER@KB SINGAPORE 415875 TEL: 9666 4445

## PROFORMA INVOICE

To: MUHAMMAD TAJUDDIN BIN ISMAIL

Invoice No.

G13/20628

Date

24/08/2021

Vehicle No.

FBP8999H

No.	Description	Qty	Unit Price		Amount	
1	REPAIR COST		\$	4,700.00	\$	4,700.00
				,		
	L			Sub-Total	\$	4,700.00
				GST 7%	\$	329.00
				Total	\$	5,029.00

Payment by cheque should be crossed and made payable to 'GARAGE 13 PTE LTD'

Issued By:

**Authorised Signature** 



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

20-11-9588

Date:

18/11/2020

INVOICE NO.

9588

Muhammad Tajuddin Bin Ismail

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Registration No.

FBP8999H

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$482.00
		Total amount	\$482.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

2

L. L. Tan (Ms)

**Principal Consultant** 

<sup>■</sup> Impact Analysis Consulting Pte Ltd
■ Impact Analysis Academy Pte Ltd
■ IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ● Infoknights International Services (Philippines)
 ● IABN Pte Ltd
 www.iaconsultingsg.com



Our reference:

20-11-9588

Date:

18/11/2020

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

**Dear Sirs** 

RE:

Road Traffic Accident on 15/10/2020

Muhammad Tajuddin Bin Ismail

In accordance with your instructions received in this office or

19/10/2020 , we ma

, we made arrangements to

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

examine the vehicle on

19/10/2020

at above-mentioned address. The following data was

recorded:

### Vehicle details

Make	Honda	Registration	FBP8999H
Model	NSS300A	Chassis	MLHNF0798J5000564
Colour	White	Gearbox	Auto
Odometer	23799km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		/

### **Tyre Depths**

Front	120/70-15	85% Pirelli
Rear	140/70-14	80% Ngel

### Impact Direction & Area of Damage:

Refer to photographs

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,700.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd
   www.iaconsultingsg.com



Our reference

20-11-9588

Date

18/11/2020

Page

2

### Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items :				
Left side frame cover Ih	1	damaged	225.00	225.00
Left side frame cover inner Ih	1	damaged	188.00	188.00
Lower cover set Ih	1	damaged	215.00	215.00
Handle bar	1	damaged	155.00	155.00
Air filter cover	1	damaged	142.00	142.00
V-belt cover	1	damaged	200.00	200.00
Fork assy	1	damaged	785.00	785.00
Side mirror lh	1	damaged	150.00	150.00
Balancer	1 set	damaged	114.00	114.00
Brake lever	1	damaged	95.00	95.00
Foot rest garnish top	1	damaged	85.00	85.00
Foot rest garnish centre	1	damaged	85.00	85.00
Foot rest garnish lower	1	damaged	79.00	79.00
Front mudguard	1	damaged	158.90	158.90
Double stand	1	damaged	135.00	135.00
	Sub- Total o	cost	2811.90	2811.90
	Percentage discount :	15%	421.79	421.79
	Sub-Total costs f	or parts	2390.12	2390.12
Special Nett Items:				
Sport rim (front)	1	damaged	598.00	598.00
Вох	1	damaged	180.00	180.00
	Sub-Total costs for parts			

Subsidiaries of Impact Analysis Consultant:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

<sup>■</sup> Impact Analysis Consulting Pte Ltd ■ Impact Analysis Academy Pte Ltd ■ IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

20-11-9588

Date

18/11/2020

**Parts Repair** 

\* \* 0.00 0.00

Sub- Total costs 0.00 0.00

Total costs for parts 3168.12 3168.12

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**