



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref:	CS/ASM21009089/Ktce2
8 SHENTON WAY #24-01 AXA TOWER			Date:	11/10/2021
SINGAPORE 068811				
ATTN: KHONG LYNN			Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5661D	Veh. Inspected	SKW 5182Z	
Policy No.	GA530184/1	Coverage (\$)	0.00	
Claim No.	S1M03GKK	Excess (\$)	0.00	
Assign From	KHONG LYNN	Assign Date	30/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHDH41CMGU655386	Colour	METALLIC GREY	
Odometer	110994 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HABILEAD	7 mm	
L/H Front Tyre	205/55 R16	HABILEAD	7 mm	
R/H Rear Tyre	205/55 R16	HABILEAD	7 mm	
L/H Rear Tyre	205/55 R16	HABILEAD	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2021	Inspection Date	30/08/2021	
Survey held at	160 Sin Ming Drive #08-03 Sin Ming AutoCity			
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	