





























































PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0750-18-N51

19 November 2018

ACCIDENT VEHICLE SURVEY REPORT

Du Yongzhi
No 8 Blk 12 Flora Drive #04-133
Singapore 506943

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLF2167R	<i>Odometer:</i>	14137km
<i>Make & Model:</i>	Toyota Sienta 1.5G A	<i>Colour:</i>	Brown
<i>Chassis number:</i>	NSP1707016602	<i>Date of accident:</i>	10/05/2018
<i>Year of Regn.:</i>	18/08/2016	<i>Date inspected:</i>	14/05/2018
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	23/05/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



