



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS/ASM21009126/Uqce2 Date: 23/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGY 1012U	Veh. Inspected	SJA 8877K
	Policy No.	GA549304	Coverage (\$)	0.00
	Claim No.	S1M03GVV	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	31/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C 180K (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WDD2040452A349397	Colour	SILVER
	Odometer	189220 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	FIRENZA	6 mm
	L/H Front Tyre	225/45 R17	FIRENZA	6 mm
	R/H Rear Tyre	225/45 R17	FIRENZA	6 mm
	L/H Rear Tyre	225/45 R17	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/08/2021	Inspection Date	06/09/2021
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	