Our Ref:	YQ2886L210826	Date:	19/09/2021
Your Ref:			

Constitution of the second

Lonpac Insurance Berhad 300 Beach Road #17-04 / 07 The Concourse Singapore 199555

Singapore 199555		
Attn: Motor Claims Department		
Dear Sir / Madam		
Traffic Accident Along 29 Woodlands Industrial E1 Singapore 757716 E	Baseme	nt
Involving YQ2886L and YP1447H On 26/08/2021		
We/I, Goldbell Leasing Pte Ltd (NRIC / ROC No: 199001196N), th - YQ2886L at all material times of the above accident. Ou Lonpac " authorized appraiser and we / I based our / my c \$\$ 5,800-00 being the repair for 03 Days (Strictly on a Wit We/I have ascertained that you were the insurers of the driver of m/	ur/my claims o thout P	vehicle was surveyed by " on his recommendation for rejudice Basis).
same was involved in the aforesaid accident with our/my m/vehicle		
We/I whereby you are the insurers of m/vehicle YP1447H and the by the negligence of your insured and as a result there of our / my m suffered loss and damage as follows:	driver	owner was caused solely
Cost of repairs	S\$	_5.800-00
LOU for pre-repair notice 02 days @ S\$ 140-00 [7545 cc][Box Truck]	•	280-00
LOU Fee for 03 days @S\$ 140-00 [7545 cc][Box Truck]		420-00
Rental Fee Invoice No:		
GIA / LTA search fee		2-00
Towing Fee (Cash Sale No)		
Survey Fee		
Total Amount	S\$	6,502-00
We/I enclose herewith copies of the supporting documents for vehicle (i) Motor Accident Report & Documents; (ii) Repair Invoices;	le no	YQ2886L as follows:-
Kindly look into the matter and let us/me hear from you on the sett as possible.	lement	of our/my claims as soon
Please remit us/me your settlement sum in favor of M/s Liu's Brot Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @	her Au Kaki	to Engineering Workshop. Bukit Singapore 417883.
Thank you.		

Yours faithfully,

<u>*</u>
The owner of m/vehicle YQ2886L
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engineering Workshop



Item

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@ymail.com

Invoice/Ref No: YO2886L210826

Original

Final Bill

Quotation /

Customer Name: Lonpac Insurance Berhad Date: 19-09-21 Vehicle No: YQ2886L Address Motor Claims Department Model/Make: Mitsubishi Fuso 300 Beach Road #17-04 / 07 The Concourse Singapore 199555 FK62FMZ1RDEC

Item No.	Descriptions Of Parts		Quotation / Estimation		Quotation / Cost Of Repair		
1	Front Windscreen Glass	\$	2,360.00	1 1	\$		
2	Windscreen Glass Weatherstrip	\$	791.50		\$		
3	Panel	\$	3,461.00		\$	-	ı
4	Panel "FUSO" Mark	\$	280.10		\$	-	ı
5	Grille	\$	1,423.00		\$	•	
6	Grille Clip 01 set	\$	42.00	SN	\$	•	
7	Grille "Mitsubishi Logo" Motif	\$	155.30		\$	-	
8	Corner Panel Garnish	\$	1,184.00		\$	•	ı
9	Corner Panel Garnish Rubber	\$	581.00		\$		ı
10	Bumper	\$	3,336.80		\$	-	ı
11	Side Mirror "Round"	\$	142.00		\$	•	
	To check all wiring & electrical component for proper function	\$	50.00		\$	-	
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test		150.00		\$	-	ı
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs		600.00		\$	-	
	To putty & spray painting & including touch up paint on accident affecte		800.00		\$	-	ı
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	1\$	60.00		\$	-	ı

Total Parts & Labour of estimate for damaged vehicle

\$ 15,416.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS: Five Thousand Eight Hundred Only



\$ 5,800.00

M/s Liu's Bro Auto Engrg Wks