Our Ref:

CC0821/\$HA9498M/CK(st)

Date:

10.09.2021

CHINA TAIPING INSURANCE CO (S)PTE L 3 ANSON ROAD #16-00

Singapore 079909

Dear Sir/Madam

Attn: Motor Claims Department

Without Prejudice

OMFORTDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

ACCIDENT ON 26.08.2021 INVOLVING SHA9498M & SLD4343X ALONG PIE TWDS TUAS

We are the authorised repair workshop for CityCab Pte Ltd , the owner of vehicle No SHA9498M, which was involved in the captioned accident with your insured vehicle No SLD4343X.

The vehicle owner and the taxi hirer/driver concerned have requested and authorised us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage of the vehicle.

As the accident was caused by the negligent act of your insured driver, we are submitting these claims for your consideration on behalf of the claimants:

Workshops Braddell

205 Braddell Road Singapore 579701

> Loyang 59 Loyang Drive

Singapore 508969 Sin Ming

383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Taxi Owner's Claim:

Hirer's Claim :		- 4		
6. Others		S\$	0.00	
5. GIA / Police Report Fee		S\$	2.00	
4. LTA Search Fee		S\$	0.00	
3. Survey Report Fee		S\$	0.00	
2. Loss of Rental	8 days x S\$ 125.19	S\$	1,001.52	
1. Cost of Repairs		S\$	19,814.39	

	IE&OE)	Total Claims	SŚ	21,457.91	
1. Loss of Income 2. Others	8 da	ays x \$\$ 80.00	S\$ S\$	640.00 0.00	

A copy each of the following supporting documents marked [X] is enclosed:

[X]	Original Repair Bill	[X]	Letter of Authority from Owner/Hirer/Operator
[X]	GIA/Police Report(s)	[X]	Rental Rate Letter
[X]	LTA/GIA Search Slip(s)	[X]	Downtime/Mileage Record
[]	Survey Report / Bill	ij	Witness Statement / Accident Scene Photo(s)
	Driver's IC/DL/VL / Road	Tax / Log	Card / Certificate of Insurance
ΪÌ	Tow Chit / PIR / Hirer's IF	AS / Oth	ners:

Kindly look into the matter and let us hear from you on the settlement of our clients' claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours sincerely Catherine Koh **CDGE Claims Department**

DID: 62148733

FAX: 62141843

Email: catherinekoh@cdge.com.sg

This is a computer-generated letter. No signature is required.

A member of



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SHA9498M , SLD4343X , ... ON 26-Aug-21 14:50

ALONG

PIE TWDS TUAS

I / We

TAN SHU KUN

(Hirer) NRIC No.: SXXXX301A

and/or

(Relief) NRIC No.: SXXXX301A

Taxi Number

SHA9498M

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

27-Aug-2021

Name of Hirer

TAN SHU KUN

Hirer NRIC

SXXXX301A

Signature:

Address

451B SENGKANG WEST WAY #10-3...

792451

Contact No.

93626686

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMHCSNW00008372001 Claim N	o: SNM21D204800/C02/SLD4343X/TANCHC
Claimant : CITYCAB PTE LTD	
Amount : S\$21,000.00 Singapore Dollars Twenty O	ne Thousand Only
I/We agree to accept the above mentioned final settlement of all claims, costs & sustained by me/us through an accident invo	disbursements for injuries / damage:
Claimant Vehicle No. : SHA9498M Insured Vehicle No. : SLD4343X	
Date of Loss : 26/08/2021 Place of Accident : PIE TOWARDS TUAS	
IN CONSIDERATION of the payment made to CHINA TAIPING INSURANCE (SINGAPORE) I discharge CHINA TAIPING INSURANCE (SINGA	PTE. LTD., I/We agree absolutely to
Insured Name : KENB KER SOON KHIAM Driver Name : KENB KER SOON KHIAM	
from all claims, present or future in resustained by me/us arising out of the said	. , , ,
I acknowledge that this payment is made we part of CHINA TAIPING INSURANCE (SINGAP	
(1) Global Sum	S\$ 21,000.00
TOTAL	S\$ 21,000.00
CLAIN DEPARTMNT COMORTDELGRO ENGINEERING PTE 59 LOYANG DRIVE Claimant Name: SINGAPORE 508969	ELTD NRIC No :

30.11.2021

Date

Please forward your payent to COMORTDELGRO ENGINEERING PTE LTD

Signature

"The contents of this documn apply to vehicle danges only. All personal injuries and danges arising therefrome excluded frorthe abit and application of this documnt"



205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701
2983 Sin Ming Drive Singapore 575717
59 Loyang Drive Singapore 508969
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649 7 Sungei Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W Page: 1

į.

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

Description: 3P 26.08.2021

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI JOB NO. 305484309

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08.2021 14:50

BANK/CHQ No.

AMOUNT

CHASSIS CODE KMHC851CVLU178518

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	28-01-0104-2028	VEHICLE NUMBER PLATE FRONT	1	55.00	0.00	55.00
0002	28-01-0104-2029	VEHICLE NUMBER PLATE REAR	1	55.00	0.00	55.00
0003	04-01-0104-0572	PANEL ASSY HOOD#	1	2,253.80	20.00	1,803.04
0004	04-01-0104-0578	COVER-FR BUMPER#	1	430.90	20.00	344.72
0005	04-01-0104-2687	MOULDING-FRONT BUMPER CTR UPR	1	368.50	20.00	294.80
0006	04-01-0104-2696	GRILLE ASSY-RADIATOR#	1	1,409.10	20.00	1,127.28
0007	04-01-0104-2701	MOULDING-FRT BPR LICENSE PLATE	1	188.00	20.00	150.40
8000	04-01-0104-0651	HINGE ASSY HOOD LH	1	118.70	20.00	94.96
0009	04-01-0104-0652	HINGE ASSY HOOD RH	1	118.70	20.00	94.96

CUSTOMERS SHALL INSPECT THEIR VEHICLED INMIDDIATED TO DO CONTRACTOR AND SHOUL WITH INSTRUCTION AND THE COMPANY OF ANY CONTRACTOR SHOULD WILL BE VEHICLES WILL BE CONTRACTOR ANY CONTRACTOR SHOULD WITH A VALUE OF THE CONTRACTOR ANY CONTRACTOR SHOULD WITH A VALUE OF THE CONTRACTOR AND CONTRACTOR SHOULD WITH A VALUE OF THE CONTRACTOR AND CONTRACTOR SHOULD WITH A VALUE OF THE CONTRACTOR OF THE CONTRACTOR AND CONTRACTOR SHOULD WITH A VALUE OF THE CONTRACTOR OF THE

ACCOUNT No.

DAMMERS, BIER

CRIOD OF DEFAULT. REASE EXAMINE THIS INVOICE IMMENIATELY UPONTHICLEST AND ADVISE THE COMPANY OF MY ENFORM OF THE WITHIN 14 DAYS OF RECENT IF THE CHIMPANY DUTY NOT HEAT PROMICEL COSTS WEEK, THE CHARGES WILL THE AT THE

CORRECT AND BINDING

omfortDelGro Engineering Pte Ltd

ead Office: 5 Braddell Road ngapore 579701

91594102 19,814.39 8010012

INVOICE No.

ndly note that no receipt shall be issued unless requested.



205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 | Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W Page: 2

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI JOB NO. 305484309

MODEL IONIQ(G3) ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08,2021 14:50

CHASSIS CODE KMHC851CVLU178518

Part No.		Qty	Unit Price	%Disc	Net
04-01-0104-0604	LATCH ASSY-HOOD	1	127.30	20.00	101.84
04-01-0104-2702	ABSORBER-FRONT BUMPER ENERGY	1	186.90	20.00	149.52
04-01-0104-2685	MOULDING-FRONT BUMPER LH	1	186.90	20.00	149.52
04-01-0104-0653	CAP-FRONT HOOK	1	29.00	20.00	23.20
04-01-0104-2871	BRACKET-FR BUMPER SIDE SUPT LH	1	35.00	20.00	28.00
04-01-0104-2971	BRACKET-FR BUMPER SIDE SUPT RH	1	35.00	20.00	28.00
04-01-0104-3818	BRACKET-FR BUMPER SIDE LH	1	28.00	20.00	22.40
04-01-0104-3918	BRACKET-FR BUMPER SIDE RH	1	28.00	20.00	22.40
04-01-0101-0111	BUMPER COVER CLIP REAR	10	2.20	20.00	17.60
04-01-0104-0634	GRILLE-FRONT BUMPER	1	318.80	20.00	255.04
04-01-0104-3849	FLAP ASSY-ACTIVE AIR UPR	1	76.90	20.00	61.52
	04-01-0104-0604 04-01-0104-2702 04-01-0104-2685 04-01-0104-0653 04-01-0104-2871 04-01-0104-2971 04-01-0104-3818 04-01-0104-3918 04-01-0101-0111 04-01-0104-0634	04-01-0104-0604 LATCH ASSY-HOOD 04-01-0104-2702 ABSORBER-FRONT BUMPER ENERGY 04-01-0104-2685 MOULDING-FRONT BUMPER LH 04-01-0104-0653 CAP-FRONT HOOK 04-01-0104-2871 BRACKET-FR BUMPER SIDE SUPT LH 04-01-0104-2971 BRACKET-FR BUMPER SIDE SUPT RH 04-01-0104-3818 BRACKET-FR BUMPER SIDE LH 04-01-0104-3918 BRACKET-FR BUMPER SIDE RH 04-01-0101-0111 BUMPER COVER CLIP REAR 04-01-0104-0634 GRILLE-FRONT BUMPER 04-01-0104-3849 FLAP ASSY-ACTIVE AIR UPR	04-01-0104-0604 LATCH ASSY-HOOD 1 04-01-0104-2702 ABSORBER-FRONT BUMPER 1 04-01-0104-2685 MOULDING-FRONT BUMPER LH 1 04-01-0104-0653 CAP-FRONT HOOK 1 04-01-0104-2871 BRACKET-FR BUMPER SIDE 1 SUPT LH 1 04-01-0104-2971 BRACKET-FR BUMPER SIDE 1 04-01-0104-3818 BRACKET-FR BUMPER SIDE LH 1 04-01-0104-3918 BRACKET-FR BUMPER SIDE LH 1 04-01-0104-3918 BRACKET-FR BUMPER SIDE RH 1 04-01-0101-0111 BUMPER COVER CLIP REAR 10 04-01-0104-0634 GRILLE-FRONT BUMPER 1	04-01-0104-0604 LATCH ASSY-HOOD 1 127.30 04-01-0104-2702 ABSORBER-FRONT BUMPER 1 186.90 04-01-0104-2685 MOULDING-FRONT BUMPER LH 1 186.90 04-01-0104-0653 CAP-FRONT HOOK 1 29.00 04-01-0104-2871 BRACKET-FR BUMPER SIDE 1 35.00 SUPT LH 35.00 04-01-0104-2971 BRACKET-FR BUMPER SIDE 1 35.00 04-01-0104-3818 BRACKET-FR BUMPER SIDE LH 1 28.00 04-01-0104-3918 BRACKET-FR BUMPER SIDE RH 1 28.00 04-01-0101-0111 BUMPER COVER CLIP REAR 10 2.20 04-01-0104-0634 GRILLE-FRONT BUMPER 1 318.80 04-01-0104-3849 FLAP ASSY-ACTIVE AIR UPR 1 76.90	04-01-0104-0604 LATCH ASSY-HOOD 1 127.30 20.00 04-01-0104-2702 ABSORBER-FRONT BUMPER 1 186.90 20.00 04-01-0104-2685 MOULDING-FRONT BUMPER LH 1 186.90 20.00 04-01-0104-0653 CAP-FRONT HOOK 1 29.00 20.00 04-01-0104-2871 BRACKET-FR BUMPER SIDE 1 35.00 20.00 04-01-0104-2971 BRACKET-FR BUMPER SIDE 1 35.00 20.00 04-01-0104-3818 BRACKET-FR BUMPER SIDE 1 28.00 20.00 04-01-0104-3818 BRACKET-FR BUMPER SIDE LH 1 28.00 20.00 04-01-0104-3918 BRACKET-FR BUMPER SIDE RH 1 28.00 20.00 04-01-0101-0111 BUMPER COVER CLIP REAR 10 2.20 20.00 04-01-0104-0634 GRILLE-FRONT BUMPER 1 318.80 20.00 04-01-0104-3849 FLAP ASSY-ACTIVE AIR UPR 1 76.90 20.00

omfortDelGro Engineering Pte Ltd

ead Office:

5 Braddell Road ngapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 8010012 91594102 19,814.39

ndly note that no receipt shall be issued unless requested.



205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

383 Sin Ming Drive Singapors 575717 7 Sungel Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W Page: 3

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI

JOB NO. 305484309

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08.2021 14:50

CHASSIS CODE KMHC851CVLU178518

S/No	Part No.		Qty	Unit Price	%Disc	Net
0021	04-01-0104-3949	FLAP ASSY-ACTIVE AIR UPR	1	76.90	20.00	61.52
0022	04-01-0104-0574	PANEL-FENDER LH#	- 1	588.80	20.00	471.04
0023	04-01-0104-3813	EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28
0024	04-01-0104-2282	COVER-RR BUMPER#	1	459.40	20.00	367.52
0025	04-01-0104-2533	MOULDING ASSY-RR BUMPER CTR	1	451.25	20.00	361.00
0026	04-01-0104-2540	COVER-RR BPR UNDER CTR	1	225.00	20.00	180.00
0027	04-01-0104-2256	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32
0028	04-01-0104-2270	EMBLEM-HYBRID	1	24.30	20.00	19.44
0029	04-01-0104-2271	EMBLEM-IONIQ	1	31.30	20.00	25.04
0030	28-01-0103-0009	REAR BOOT LOGO CCTPL	1	30.00	0.00	30.00
0031	28-01-0103-0010	REAR BOOT TEL NUMBER CCTPL	1	35.00	0.00	35.00

OWNERS: FISK. CUSTOMERS SHALL INSPECT THEIR VEHILL'S INMUDIATELY HATH CITEVITY WITH THAT WITHIN THAT IT IN SHITE THE OTICE IN WRITING TO THE COMPANY OF ANY CONTRAINT OF THE WHILE THE WHILL BY THE HEIL HE WILL HE WILL HE WAS TO THE

NTEREST OF THE REE MONTH WILL THE CONTROL OF A DECEMBER OF A DESCRIPTION OF A DESCRIPTION OF A DECEMBER OF THE CONTROL OF A DESCRIPTION OF A D

omfortDelGro Engineering Pte Ltd

ead Office:

5 Braddell Road ngapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 8010012 91594102 19,814.39

ndly note that no receipt shall be issued unless requested.



205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W Page: 4

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI

JOB NO. 305484309

MODEL IONIQ(G3) ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08.2021 14:50

CHASSIS CODE KMHC851CVLU178518

S/No	Part No.		Qty	Unit Price	%Disc	Net
0032	28-01-9999-2026	APP LOGO REAR BONNET CCPL	1	30.00	0.00	30.00
0033	04-01-0104-2380	LATCH ASSY-TAIL GATE	1	141.00	20,00	112.80
0034	09-01-9999-0068	REVERSE SENSOR ASSY*	1	180.00	0.00	180.00
0035	04-01-0104-1150	PROTECTOR MAT	1	50.00	0.00	50.00
0036	04-01-0104-2288	BEAM-RR BUMPER	1	394.80	20.00	315.84
0037	04-01-0104-2419	BEAM COMPLETE-FR BUMPER	1	1,075.10	20.00	860.08
0038	04-01-0104-2835	LAMP ASSY-HEAD LH#	1	1,993.65	20.00	1,594.92
0039	04-01-0104-0641	CARRIER ASSY-FRONT END MODULE#	1	949.30	20.00	759.44
0040	16-01-0104-2016	BLOWER ASSY-RADIATOR	1	1,226.60	20.00	981.28
0041	16-01-0104-2076	RADIATOR ASSY-INVERTER	1	884.80	20.00	707.84
0042	16-01-0104-0103	RADIATOR ASSY	_ 1	710.50	20.00	568.40
0043	01-01-0104-0039	CONDENSER ASSY-COOLER	1	663.60	20.00	530.88

omfortDelGro Engineering Pte Ltd

ead Office:

5 Braddell Road ngapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 91594102 19,814.39 8010012

ndly note that no receipt shall be issued unless requested.



205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops

205 Braddell Road Singapore 579701 383 Sin Ming Drive Singapore 575717 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

7 Sungei Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 5

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI **JOB NO.** 305484309

MODEL IONIQ(G3) ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08.2021 14:50

CHASSIS CODE KMHC851CVLU178518

S/No	Part No.		Qty	Unit Price	%Disc	Net
0044	04-01-0104-2226	LAMP ASSY-LICENSE PLATE	1	85.30	20.00	68.24
0045	04-01-0104-2175	SYMBOL MARK-H	1	24.30	20.00	19.44
0046	20-01-9999-2025	PRESTONE ANTIFREEZE COOLANT PREMIX 50-50	2	22.50	20.00	36.00
			SUB-TOTAL	:		15,250.52
JOB N	ATURE	-				
0001	L	BUMPER COVER CLIP REAR		22.00		17.60
0002	PB	PANEL BEATING SHA9498M		1,750.00		1,750.00
0003	SP	SPRAYPAINT CHARGE		1,250.00		1,250.00
0004	Ľ	REMOVE/ REFIX AIRCON & REFILL GAS		60.00		60.00
0005	L	REMOVE/ REFIX RADIATOR		30.00		30.00
0006	23-01 TEARCHAILLE	TOWING FEE		60.00		60.00

OTICE IN WRITING TO THE CLIMPARTY OF THE CHAPLET HER A SAY PARTY WAS IN HIGHER TO THE SMOUNT WE WILL BE CHAPLET HER AND NOT HARD THE OWN DATE OF SANDER AND NOT HARD THE OWN DATE OF SANDER AND NOT HARD THE OWN DATE OF SANDER THE CHAPTER THE SANDER OF DETAILS.

LEASE EXAMINE THIS INVOICE HARDONTELY INCLUDE REQUIRE VALUE FOR THE CONTRACT OF ANY WALL WALL TO AND SINDING.

omfortDelGro Engineering Pte Ltd

ad Office:

5 Braddell Road ngapore 579701

ndly note that no receipt shall be issued unless requested.

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91594102	19,814.39	
		<u> </u>	人



206 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

383 Sin Ming Drive Singapore 575717 7 Sungel Kadut Way Singapore 728791 320 Ubi Road 3 Singapore 408649

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 6

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA9498M

INV. NO/DATE 91594102 09.09.2021

MAKE HYUNDAI JOB NO. 305484309

MODEL IONIQ(G3) ODOMETER READING

DATE OF REG 09.10.2019

DATE/TIME IN 26.08.2021 14:50

CHASSIS CODE KMHC851CVLU178518

S/No	Part No.		Qty	Unit Price	%Disc	Net
0007	20-00	TUFF COAT ON AFFECTED PARTS.		60.00		60.00
8000	17-01	CHECK ALL LIGHTING		40.00		40.00
			SUB-TOTAL	12		3,267.60

Items total

18,518.12

Add GST @

7.000 %

1,296.27

Invoice amount

19,814.39

Issued by : KATHERINETAN 09.09.2021 13:53:56 Repair type : CFSO/57/57 Payment Type/Term: /Credit 30 days

omfortDelGro Engineering Pte Ltd

ead Office: 5 Braddell Road

ngapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No. 8010012 91594102 19,814.39

ndly note that no receipt shall be issued unless requested.

Our Ref: CC21080413

Date: 09 September 2021



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

26/08/2021

@ 14:50 hrs

ALONG

PIE TWDS TUAS

INVOLVING

SLD4343X, SKX6852L, SJP9550S

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA9498M (the "Taxi"). The Taxi was hired to TAN SHU KUN IC NO SXXXX301A a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

95 T
Acaidm Remain
12851
SV7
367 1529
3/1 /13/1
SK1 121 12
2251 1255
246151
MILEAGE READING

INSURER ENQUIRY **Find insurer** Vehicle reg. no.

SLD4343X

Date of Accident

26/08/2021

Reset

% RESULT & RECEIPT

TP Insurer Enquiry	
Insurance China 1	aiping Insurance (Sing
Period of Insurance	17/12/2020 - 16/12/2021
Requested By	Xiao Yan (COMFORTDEL
Requested Date	27/08/2021 11:33

Payment details

Request Amount: \$\$1.87 GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: M400017735

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 20 October 2021 11:47 AM

To: JFU.LEI@LIVE.COM

Subject: Claim Notification - ACCIDENT INVOLVING SLD 4343X(CHINA TAIPING) / SHA

9498M/ OTHERS AT/ALONG PIE TOWARDS TUAS ON 26/08/2021

20 Oct 2021

Mr Kenb Ker Soon Khiam [By Email Only]

Dear Sir/Madam,

You Ref: SLD4343X

Our Ref: CC3/CTI21009142/Vpa3

ACCIDENT INVOLVING SLD 4343X(CHINA TAIPING) / SHA 9498M/ OTHERS AT/ALONG PIE TOWARDS TUAS ON

26/08/2021

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, China Taiping Insurance (Singapore) Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SHA9498M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 07 days from the date of this letter.

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com | Fax: 6741 4108 HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 26 November 2021 4:30 PM

To: Tan Chew Chik Jacqueline
Cc: Admin A; Claims Dept of CTI

Subject: RE: [Seek Mandate] - SNM21D204800/C02/SLD4343X/TANCHC / FW: Direct

Settlement - Accident Involving SLD4343X (OI: CTI - TBA) and SHA9498M (TP: LKK

REF - CC3/CTI21009142/Vba3) on 26/08/2021

Dear Sirs/Mdm,

For an update, we have settled the matter at a global sum of \$21K(all-in) with third party repairer.

We are pending for signed DV from third party and will proceed to close file once DV received.

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com | Fax: 6741 4108 HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Tan Chew Chik Jacqueline < jacqueline.tan@sg.cntaiping.com>

Sent: Wednesday, 24 November 2021 10:58 AM **To:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: [Seek Mandate] - SNM21D204800/C02/SLD4343X/TANCHC / FW: Direct Settlement - Accident Involving

SLD4343X (OI: CTI - TBA) and SHA9498M (TP: LKK REF - CC3/CTI21009142/Vba3) on 26/08/2021

Dear Hsiao Tong,

Please proceed as proposed.

** Note: Please cc to claimsdept@sg.cntaiping.com when you reply to us.

NOTICE:

In response to the escalating Covid-19 cases, please refrain from sending hardcopy documents to us as delay is to be expected for handling hardcopy documents. All correspondence should be made via email claimsdept@sg.cntaiping.com or fax at 6224 7175. Any inconvenience caused is much regretted.

Regards,

Jacqueline Tan

Senior Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909 DID: (65) 6389 6185 | Tel: (65) 6389 6116 | F: (65) 6224 7175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Sent: Sunday, 14 November 2021 12:46 PM

To: Tan Chew Chik Jacqueline < jacqueline.tan@sg.cntaiping.com>

Cc: Admin A <admin-a@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: [Seek Mandate] - SNM21D204800/C02/SLD4343X/TANCHC / FW: Direct Settlement - Accident Involving

SLD4343X (OI: CTI-TBA) and SHA9498M (TP: LKK REF-CC3/CTI21009142/Vba3) on 26/08/2021

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Your ref: SNM21D204800/C02/SLD4343X/TANCHC

LKK ref: CC3/CTI21009142/Vpa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLD4343X(CHINA TAIPING)/ SHA9498M(TP) / OTHERS ON 26/08/2021

We refer to the above matter.

SLD4343X(OI) -> SHA9498M(TP) -> SKX6852L -> SJP9550S

This is a 4 vehicles chain collision whereby our insured was the last vehicle. In accordance with the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer repairer "ComfortDelgro Engineering Pte Ltd" at \$21,217.91(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair(w/GST)	\$ 40,245.18	\$ 19,814.39 (\$18,518.12 + 7%GST)
2. Loss of Rental (8days x \$125.19)	\$ 1,001.52	\$ 1,001.52 (8days x \$125.19)
3. Loss of Income (8days x \$80.00)	\$ 640.00	\$ 400.00 (8days x \$50.00)
4. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 41,888.70	<u>\$ 21,217.91</u>

Surveyor recommended 6 days for repair + 1Sunday + 1PRS = 8days.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval / instruction.

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards, **Hsiao Tong, Chew** | Case Handler **LKK Auto Consultants Pte Ltd**

Phone: 6742 3197 | email: chewht@lkkauto.com | fax: 6741 4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Chew Chik Jacqueline < jacqueline.tan@sg.cntaiping.com>

Sent: Thursday, 2 September 2021 10:27 am

To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>; Jasper Chua (LKK Auto) < jasperchua@lkkauto.com>; Admin A admin-a@lkkauto.com>; Admin A

Subject: RE: SNM21D204800/C02/SLD4343X/TANCHC / FW: Direct Settlement - Accident Involving SLD4343X (OI: CTI - TBA) and SHA9498M (TP: LKK REF - CC3/CTI21009142/Vba3) on 26/08/2021

Hi Mei Kwan.

Enclosed Insd SAS report for your necessary action.

** Note: Please cc to com when you reply to us.

NOTICE:

In response to the escalating Covid-19 cases, please refrain from sending hardcopy documents to us as delay is to be expected for handling hardcopy documents. All correspondence should be made via email claimsdept@sg.cntaiping.com or fax at 6224 7175. Any inconvenience caused is much regretted.

Regards,

Jacqueline Tan

Senior Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909 DID: (65) 6389 6185 | Tel: (65) 6389 6116 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Wednesday, 1 September 2021 3:54 PM

To: Meikwan@lkkauto.com; jasperchua@lkkauto.com; Admin A <admin-a@lkkauto.com>; Tan Chew Chik Jacqueline <iacqueline.tan@sg.cntaiping.com>

Cc: Claims Dept of CTI < claimsdept@sg.cntaiping.com>

Subject: O/R: SNM21D204800/C02/SLD4343X/TANCHC / FW: Direct Settlement - Accident Involving SLD4343X (OI: CTI - TBA) and SHA9498M (TP: LKK REF - CC3/CTI21009142/Vba3) on 26/08/2021

Dear all,

Please note that officer in charge for this case is Jacqueline Tan.

Claim no SNM21D204800/C02/SLD4343X/TANCHC.

Dear Jacqueline,

Pls revert LKK.

NO TICE:

In response to the escalating Covid-19 cases, please refrain from sending hardcopy documents to us as delay is to be expected for handling hardcopy documents. All correspondence should be made via email claimsdept@sq.cntaiping.com or fax at 6224-7175. Any inconvenience caused is much regretted.

Thank you

Chong Boon Sen

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮

城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Sent: Tuesday, 31 August 2021 5:38 PM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com>

Cc: Jasper Chua (LKK Auto) < jasperchua@lkkauto.com>; Admin A < admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SLD4343X (OI: CTI - TBA) and SHA9498M (TP: LKK

REF - CC3/CTI21009142/Vba3) on 26/08/2021

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Sirs/ Madam,

We refer to the above matter.

We have inspected TP vehicle SHA 9498M at M/s ComfortDelGro Engineering Pte Ltd (Loyang) on a WP basis and TP repairer proposed for a direct settlement

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jasper.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.