

**\*PAIR ESTIMATE\***

VEHICLE NO SHC2348Z

DATE 26.08.21

MAKE :14.11.2019

MODEL : HYUNDAI IONIQ G3

		CHIANG/NTUC		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR DOOR PANEL RH			\$1,789.90
1	FRONT DOOR PROTECTOR RH			\$110.10
1	REAR DOOR PROTECTOR RH			\$125.30
	<b>SUB TOTAL</b>			<b>\$2,025.30</b>
	<b>LESS 20%</b>			<b>\$405.06</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,620.24</b>
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
1	REAR DOOR COMFORT APP STICKER			\$80.00
				<b>\$139.50</b>
	<b>Labour Charge</b>			
	Panel Beating			\$600.00
	Spray Painting Charge			\$900.00
	Remove/refix door parts.			\$90.00
	Check Wiring			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,650.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$3,409.74</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan LKH

82235769 thuan@lkhauto.com

27/8/21 1630

PIP bfr paint pictures photos  
2days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: