

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 13 March 2023 10:09 AM
To: Irene Tay
Cc: Admin A; claimsdept@sg.cntaiping.com
Subject: [SEEK MANDATE] - Your ref: SNM21D204925 // LKK ref : CC6/CTI21009164/Apa3q2
[ACCIDENT INVOLVING YP4357P(CHINA TAIPING) AND GBL350C(TP) ON 25/08/2021]
Attachments: LKK SURVEY REPORT & PHOTOS.pdf; LETTER TO OI.pdf; LOD_GBL350C.pdf

Your ref: **SNM21D204925**
LKK ref : CC6/CTI21009164/Apa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING YP4357P(CHINA TAIPING) AND GBL350C(TP) ON 25/08/2021

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer "J-MART MOTOR PTE LTD" at **\$10,000.77(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 7% GST)	\$ 15,100.89	\$ 9,000.77 (\$8,411.93 + 7%GST)
2. Loss of RENTAL (10days x \$120.00)	\$ 1,200.00	\$ 1,000.00 (10DAYS X \$100.00)
Total	\$ 16,300.89	<u>\$ 10,000.77</u>

Surveyor recommended 9days for repair + 1SUNDAY = 10DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 10/03/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

