

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	F	Ref:	CS/CTI21009170/c		
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	1	Date:	01/09/2021	
			(Code:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJL 9146Y	Veh. Inspected		SBN 6888T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D204853/C02/SJL9146Y /TANKL	Excess (\$)		0.00	
	Assign From	TAN KAH LEONG	Assign Date		01/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	ssis No. Colour				
	Odometer	- Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	27/08/2021	Inspection Date	!		
	Survey held at	CHENG HOE MOTOR SERVICE				
		10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					