

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
C1 Reg B
Money After Paint
5 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Thrd Party

Date: 31.08.2021

Accident Date : 27.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Kia Forte" Reg. No. SGC6543L Claiming Against Your Insured Reg. No. SMR4332S			
1pc	Rear Bumper	4.50	856.00 ✓
12pcs	Rear Bumper Clips		54.00 ✓
1pc	Rear Bumper Sponge		235.00 ✓
2pcs	Rear Bumper Brackets	39.00	78.00 ✓
1pc	Rear Bumper Reinforcement		434.00 ✓
1pc	Rear Bumper Lower Lip		245.00 ✓
2pcs	Rear Bumper Reflectors	132.00	264.00 ✓
3pcs	Rear Bumper Lower Retainers	45.00	135.00 ✓
1pc	Rear Bumper Auto Boot Sensor		125.00 X
1pc	Boot Emblem		43.00 ✓
1pc	Boot Badge FORTE		42.00 ✓
1pc	Boot Badge K3		39.00 ✓
1pc	End Panel		335.00 X
1pc	End Panel Garnish		165.00 ✓
1pc	Front Bumper	4.50	820.00 ✓
10pcs	Front Bumper Clips		45.00 ✓
1pc	Front Bumper Sponge		116.00 ✓
1pc	Front Bumper Reinforcement		423.00 ✓
1pc	Front Bumper Number Plate Holder		47.00 ✓
1pc	Front Bumper Center Air Grille		79.00 ✓
1pc	Front Bumper Emblem		42.00 ✓
1pc	Grille		324.00 ✓
2pcs	Headlamp Assy (HID)	1,850.00	3,700.00 ✓
			8,646.00
	Less 10%		864.60
			7,781.40
	Rear Bumper Reverse Sensor		280.00 SN
	Boot Badge C&C		50.00 SN
	Front Number Plate		45.00 SN
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, Rewiring etc.		120.00 Sol
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 X
	To Supply End Panel Body Sealant		60.00 X
		C/F	8,416.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AtG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 31.08.2021

Accident Date : 27.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Forte" Reg. No. SGC6543L Claiming Against Your Insured Reg. No. SMR4332S		
		B/F	8,416.40
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 ✓
	To Conduct Front Electrical Check, Focus Headlamp		30.00 ✓
	Labour Charge - Panel Beating, Repairing Rear Chassis Member, Boot Lid, Floor Panel, Spare Tyre Panel, Front Support etc. Cnt, Weld End Panel and Parts Replacement		1,100.00 ✓
	To Respray Affected Areas (Big Veh)		1,000.00 ✓
		Total :	<u>10,646.40</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: