

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21009187/Utf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	27/09/2021	
			Code	: AGI	
1.	I. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 120S	Veh. Inspected	SLL 5964E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10011476/CD	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	01/09/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	KMHD841CMHU365766	Colour	SILVER	
	Odometer	125849 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	30/08/2021	Inspection Date	01/09/2021	
	Survey held at	23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)			
	Repairer	AIM HENG CAR SERVICE PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: