



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21009188/Gny3e2 Date: 03/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 32T	Veh. Inspected	SGQ 1706T
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/08/21/1026	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	01/09/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ 1.4A	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMGD18507S202802	Colour	YELLOW
Odometer	287158 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R15	HANKOOK	6 mm
L/H Front Tyre	195/50 R15	HANKOOK	6 mm
R/H Rear Tyre	195/50 R15	HANKOOK	6 mm
L/H Rear Tyre	195/50 R15	HANKOOK	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	20/08/2021	Inspection Date	07/09/2021
Survey held at	56 LOYANG WAY #04-04		
Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days