

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Survey Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 52938144C

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21009193/Gqf3 Date: 01/09/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY		Veh. Inspected	SKG 6846U
Policy No.	B 300445396 CAR		Coverage (\$)	0.00
Claim No.	261912 CAR		Excess (\$)	0.00
Assign From	MARVIN CHIA		Assign Date	01/09/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/08/2021		Inspection Date	03/09/2021
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				