

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16

079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	2	LIST ITEMS :		
2.	1	Front headlamp / RH / RR (supp)	341.00	682.00
3.	1	Front door		748.00
4.	1	Front fender / RL (supp)		88.00
5.	1	Front bonnet		297.00
6.	1	Front bumper		242.00
7.	1	Front grille (top) / 1/3 (supp)		132.00
8.	1	Front grille lower panel		165.00
9.	1	Front grille		275.00
10.	2	Bumper retainers	77.00	154.00
11.	1	Front panel / BT (supp)		44.00
12.	1	Front door weatherstrip (inner) / RL (supp)		132.00
13.	1	Front door glass rubber / RL (supp)		66.00
14.	1	Inter Cooler / BT (supp)		660.00
15.	1	Door check / BT (supp)		88.00
16.	1	Front bonnet cable / RL (supp)		60.50
17.	1	Front bonnet lock / BT (supp)		77.00
18.	1	Front door glass		253.00
19.	1	Front door rubber / RL (supp)		187.00
20.	1	Door pillar		165.00
21.	1	Wiper link / BT (supp)		275.00
22.	2	Door hinge	60.50	121.00
23.	1	Door inner lock		242.00
24.	1	Front LH pillar out / BT (supp)		264.00
		Panel LH cowl top / RL (supp)		66.00

CONTINUE / ...

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16
079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	Headlamp mtg bracket / PR (Supp)		55.00
26.	1	Door striker / BT (Supp)		38.50
27.	1	front bumper Grille LH / mis (Supp)		44.00
28.	1	Front door suduff plate LH		143.00
29.	1	Headlamp bracket / PR (Supp)		16.50
30.	2	Front bonnet hinges / BT (Supp)	44.00	88.00
31.	1	Front door regulator / BT (Supp)		132.00
32.	1	Radiator Assy		770.00
33.	1	Side mirror		220.00
34.	1	Radiator spare tank / OR (Supp)		198.00
35.	1	Wiper tank		66.00
36.	1	Support panel / buc (Supp)		198.00
37.	1	Radiator fan cowling / de (Supp)		154.00
38.	1	Emblem / RL (Supp)		44.00
39.	1	Front door cardboard		440.00
40.	1	Front windscreen glass		198.00
41.	2	Silicone seal	11.00	22.00
42.	2	Silicone seal	13.20	26.40
43.	6	clip / N/A (Supp)	3.30	19.80
44.	1	Front number plate		12.10
45.	1	Rear lamp (LH) / Dis (Supp) - \$1250		55.00
46.	1	Air Con Coil		2,530.00
47.	1	Air con condenser / Dis (Supp) - \$500		
48.	1	Air con blow system / Dis (Supp) - \$550		
List TotalS\$:				10,953.80 ✓

CONTINUE / ...

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No. : 6741 5520 / 6741 1339 Fax No. : 6741 5808

E-Mail : kimsengteck_motorworks@yahoo.com.sg

Website : kstteam@singnet.com.sg

Tax Reg. No. : M9-0002075-E Buss. Reg. No. : 27157400/C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07 - 16
079120

Attention : Motor Claim Department

Tax Invoice : CI200789

Date : 31/08/2021

Vehicle Num. : GBF 635M

Make/Model : Toyota Hiace Van Turbo 5 DR-10 / 06

Chassis/Eng# : JTFHT02P000197960/1KD2619760

Accident Date : 26/08/2021

Claim No. :

Reference :

Policy No. : 999993603

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
1		Labour for remove & refix air con system and refill gas	180.00	180.00 120
1		Labour for remove & refix windscreen	120.00	120.00 ✓
1		Labour for remove & refix dashboard	300.00	300.00 200
1		Labour for repair light wiring	60.00	60.00 30
1		To check from wiring & front Headlamp	40.00	40.00 10
1		To dismantle & refix cabin LH handside carpet & timing	160.00	160.00 80
1		To respray paint from affected portion	1,500.00	1,500.00 1400
1		To straighten & knock & cut affected panel & renew recommend Parts	1,800.00	1,800.00 1600
1		To dismantle & refix rear cabin timing & garnish to enable repair	45.00	45.00 20
1		to spray paint LH rear portion	800.00	800.00 X
		Labour Total S\$:		5,005.00 3580

14533.8

E. & O.E.	Total S\$:	15,958.80
	Excess Amount S\$:	1,000.00
	Net Amount S\$:	14,958.80
	GST @ 7% S\$:	1,047.12
	Amount Due S\$:	16,005.92
		=====



for KIM SENG TECK MOTOR WORKS