

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

Business Regn. No. 10115500W

BIKE NO: JPK3064

INVOICE NO: 0016/2022

Messer

HAIRIANSYAH BIN PUTRI

Date : 07/09/2022

BLK 23A QUEEN'S CLOSE #02-195

D.O.A. : 24/02/2022

SINGAPORE 140023

MAKE/MOD YMH LC135

S/N	Description	Amount
1	HEADLIGHT ASSY	\$185.00
2	METER ASSY	\$320.00
3	SIGNAL LIGHT ASSY	\$165.00
4	HANDLER BAR	\$98.00
5	HANDLER BRACKET	\$85.00
6	COWLING STAY	\$65.00
7	STEERING CON	\$110.00
8	UNDER BRACKET	\$195.00
9	FORK ASSY X2	\$380.00
10	FRONT FENDER	\$85.00
11	FRONT WHEEL SHAFT	\$45.00
12	FRONT WHEEL RIM	\$398.00
13	FRONT BRAKE DISC	\$185.00
14	FRONT HANDLER COVER UPPER	\$95.00
15	REAR HANDLER COVER UPPER	\$85.00
16	TOP FRONT PANEL	\$195.00
17	PANEL COVER	\$110.00
18	PANEL INNER (1)	\$80.00
19	MIRROR	\$45.00
20	BRAKE LEVER	\$110.00
21	METER GEAR	\$85.00
22	L/H LEG SHIELD	\$185.00
23	R/H LEG SHIELD	\$185.00
24	L/HFRONT BODY LOWER	\$45.00
25	R/H FRONT BODY LOWER	\$45.00
26	L/H AIR GUIDE	\$25.00
27	R/H AIR GUIDE	\$25.00
28	PRESS BODY	\$780.00
29	RADIATOR	\$380.00
30	COOLANT	\$35.00
31	WINDSHIELD	\$68.00
32	REAR BOX	\$580.00
33	BOX RACK	\$180.00
34	EXHAUST ASSY	\$495.00
35	TOW	\$80.00
36	LABOUR	\$500.00
37	TOTL REPAIR COST -10%	\$5,612.10
38	LOSS OF USE (7 X \$35)	\$245.00
39		
40	TOTAL:	\$5,857.10