



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009206/Ktf3n2	Date: 13/10/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 107E	Veh. Inspected	GBH 8303H
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10011436/HA	Excess (\$)	0.00
	Assign From	FRAULEINE KHOO	Assign Date	01/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y00K210024	Colour	SILVER
	Odometer	77143 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	OHTSU	9 mm
	L/H Front Tyre	195 R15X8	OHTSU	9 mm
	R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm
	L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/08/2021	Inspection Date	20/09/2021
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	