

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2255G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COMPANY STICKER (SN)	NECESSARY	50.00	30.00
1	LALAMOVE STICKER (SN)	NOT INSURED	300.00	-
1	RHF DOOR PANEL ASSY (SN)	DENTED	1,462.00	1,462.00
1	RH DOOR WEATHERSTRIP (SN)	NOT NECESSARY	93.00	-
1	RH DOOR WEATHERSTRIP (SN)	NOT NECESSARY	79.00	-
1	RHF PROTECTOR PANEL (SN)	CUT	336.00	336.00
1	RHF DOOR ADHESIVE TA (SN)	NECESSARY	10.00	10.00
1	RH SLINDING SIDE DOO (SN)	TO REPAIR SEE LABOUR	1,590.00	-
1	RH SIDE SILL SEAL (SN)	NOT NECESSARY	98.00	-
1	RH SLIDE DOOR PROTEC (SN)	CUT	112.00	112.00
1	RIGHT REAR WING (SN)	TO REPAIR SEE LABOUR	1,747.00	-
			5,877.00	1,950.00
	<u>LABOUR</u>			
	DIAGNOSTIC / SCANNING.		250.00	250.00
	TO TRANSFER DOOR AND RHF SLIDING DOOR MECHANISM AND COMPONENT PARTS.		1,280.00	320.00
	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY FACILITATE RENEWEL RHR OUTER QUARTER PANEL.	NOT NECESSARY	1,280.00	-
	TO REPLACE RHF DOOR PANEL, RHS SLIDING DOOR PANEL, ETC - TO CUT & RE-WELD RHR OUTER QUARTER PANEL TO REPAIR RHS SIDE SILL STRAIGHTEN, REFORM, ALIGN ON RHS ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF RH SLINDING SIDE DOO AND RIGHT REAR WING.		3,840.00	1,600.00
	TO APPLY SEALANT KIT ON NEW PANEL.		300.00	100.00
	SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS.		2,750.00	1,650.00
			9,700.00	3,920.00
	GRAND TOTAL		15,577.00	5,870.00

Report Ref No. CS/UOI21009207/Auf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		5,870.00
LESS EXCESS		-500.00
NETT LIABILITY		5,370.00

Report Ref No. CS/UOI21009207/Auf3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.