

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	SURANCE (S) PTE LTD		Ref:	CS/CTI21009210/c
	3 ANSON ROAD # SPRINGLEAF TOV		Date:	01/09/2021	
				Code:	СТІ
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMJ6399D	Veh. Inspected		PC 5492A
	Policy No.		Coverage (\$)		0.00
	Claim No.	SNM21D204901/C02/SMJ6399 D/TAYHP	Excess (\$)		0.00
	Assign From	TAN KAH LEONG	Assign Date		01/09/2021
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	Steering			
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5. General Information					
	Accident Date	25/08/2021	Inspection Date		
	Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING			
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				