			,		
Date / Time	Action / Instruction				_
	mv: suk				
	rebate: 25 535				
	NV 28465	,			
	张 :				
	Confirmed final	fig P/P \$6448.38	, 6 repair day	S	
	(RED \$1	683.83; 21%)			_
lase/Time_Fla Pas	: Proll, Ro	port . [Days Of Repair:	6 .	

WAR GIRL IN

: Proll. Roport 14/9 TYPIST : Final Roport Date Time File Return 107

Add Fee:

Resurvey No. of Trlp: Survey Fee: Transportation; : Site Insp (\$ S + #S. SI Interview Frinitis Tech. Inve (\$ Olive

ework Formus :

\$6448.38

7014.

AB ENGINEERING PTE LTD

Co. Reg No: 201217273R 25 Senang Crescent, Singapore 416589

Fax: 6747 7791 Office: 6749 9699

ABWin Leasing Pte Ltd

ESTIMATE

Date : Model: LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey beforeselfer sorely painting
- . To display demaged pitella) during resurvey
- · Parts purs are stripe * to confirmation
- . Third party survey is on a Without Prejudice The is
- . No illingal modification(s) is all-wed.
- . Supplementary demis) must be resurveyed a. . is subject to final approval from Insurance Contoury

Actypyliggagd by Repairer

Vehicle No

SI208H3434X Dalgissan NV350

NETT ITEMS	5/No	Description	QTY		U/PRICE	_	AMOUNT
1 tail gate 1 5 1,998.30 5 1,998.30 (Ut) 2 tail gate lock 1 5 297.10 5 297.10 3 tail gate emblem 1 5 69.40 5 69.40 4 tail gate hinge RN&LH 2 5 64.20 5 128.40 5 tail gate name plate Ny350 URVAN 1 5 110.00 5 110.00 7 tail gate name plate Ny350 URVAN 1 5 110.00 5 110.00 7 tail gate inner board 1 5 198.00 5 198.00 198.00 9 rear bumper 1 5 667.20 5 667.20 5 667.20 10 rear bumper reinforcement 1 5 208.00 5 208.00 11 rear bumper reinforcement 1 5 208.00 5 208.00 12 rear bumper reinforcement 1 5 358.00 5 359.00 13 step garnish 1 5 155.00 5 155.00	-						/
2 tail gate look			1	\$	1,998.30	\$	1,998.30 (U+
1 \$ 69.40			1	\$	297.10	\$	297.10
4 tail gate hinge RH& LH 5 tail gate absorber RH&LH 5 tail gate absorber RH&LH 2 \$ 5.237.50 \$ 475.00 7 tail gate name plate NV350 URVAN 1 \$ 110.00 \$ 110.00 7 tail gate name plate NV350 URVAN 1 \$ 110.00 \$ 134.30 8 tail gate inner board 1 \$ 198.00 \$ 198.00 9 rear bumper 1 \$ 667.20 \$ 667.20 \$ 667.20 10 rear bumper reinforcement 1 \$ 208.00 \$ 208.00 11 rear bumper reinforcement 1 \$ 208.00 \$ 208.00 11 rear bumper reinforcement 1 \$ 5.85.00 \$ 85.00 12 rear bumper centre protector 1 \$ 85.00 \$ 85.00 13 step garnish 1 \$ 155.00 \$ 155.00 14 lend panel inner 1 \$ 460.80 \$ 460.80 15 tail lamp RH & LH 2 \$ 247.30 \$ 494.60 15 tail lamp RH & LH 2 \$ 5.5597.90			1	\$	69.40	\$	69.40 NIC
Stall gate absorber RH&LH			2	\$	64.20	\$	128.40 N.X
6 tail gate name plate NV350 URVAN			2	<u> </u>		_	475.00 1 🗶
State 1			1	<u></u>		<u> </u>	110.00
Stall gate inner board 1 S 198.00 S 198.00 Cq + 10 Fear bumper 1 S 667.20 S 667.20 Cq + 10 Fear bumper enforcement 1 S 208.00 S 208.00 T Cq + 10 Fear bumper side retainer RH&LH 2 S 58.40 S 116.80 T Cq + 10			1			\$	134.30 1.
Second S			_	<u> </u>		_	100.00 /
10 rear bumper reinforcement				<u> </u>		-	667.20
11 rear bumper side retainer RH&LH			_	<u> </u>		-	200 00 []
13 step garnish 1	11	rear bumper side retainer RH&LH		_		_	116.80 NEC
13 step garnish 1				Ś	85.00	\$	85.00 NCC
15 tail lamp RH & LH			1	÷	155.00	\$	155.00 0
15 tail lamp RH & LH			_	_	460.80		460.80 7.
Less 10%: Less 10%: Synett 1	15	tail lamp RH & I H			247.30	\$	494.60 7.
Less 10%: Synth S		Contemp (are en		·		\$	5,597.90
S/NETT 1.000.00 1.000		less 10% :					559.79
S/NETT 16 end panel outer 1		2000 2070 1		_		_	5.038.11
16 end panel outer 17 reverse sensor 18 sticker - 70km/h 19 rear windscreen glass sealant 10 \$ 10.00 \$						<u> </u>	3,555.22
16 end panel outer 17 reverse sensor 1 \$ 280.00 \$ 280.		S/NFTT				-	
17 reverse sensor 1 \$ 280.00 \$ 280.00 rec 18 sticker - 70km/h 1 \$ 10.00 \$ 10.00 rec 19 rear windscreen glass sealant 1 \$ 50.00 \$ 50.00 rec 20 To check wiring To dismantle and renew the reverse sensor, re-set of same To dismantle and reinstate the rear windscreen glass 22 to the new tail gate To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 280.00 rec \$ 30.00 rec \$ 3	16	·	1	\$	174.10	Ś	174.10
18 sticker - 70km/h 19 rear windscreen glass sealant 1 \$ 10.00 \$ 10.00 19 rear windscreen glass sealant 1 \$ 50.00 \$ 50.00 10			1			Ś	280,00 (ut 700 (ut
19 rear windscreen glass sealant 1 \$ 50.00 \$ 50.00 To check wiring To dismantle and renew the reverse sensor, re-set of same To dismantle and reinstate the rear windscreen glass 21 to the new tail gate To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 200.00							
20 To check wiring To dismantle and renew the reverse sensor, re-set of 21 same To dismantle and reinstate the rear windscreen glass 22 to the new tail gate To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 30.00 \$ \$80.00 \$ \$ 150.00 \$ \$ 120.00 \$ \$ 1,000.00 \$ \$ 1,000.00						_	
To dismantle and renew the reverse sensor, re-set of same \$80.00 To dismantle and reinstate the rear windscreen glass to the new tail gate To dismantle and transfer/refit the tail gate fittings to the new tail gate, adjust of same \$120.00 To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced \$26 panels \$200.00	15	Teal Willuscreen glass sectoric		<u> </u>	30.00	<u> </u>	
To dismantle and renew the reverse sensor, re-set of same \$80.00 To dismantle and reinstate the rear windscreen glass to the new tail gate To dismantle and transfer/refit the tail gate fittings to the new tail gate, adjust of same \$120.00 To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced \$26 panels \$200.00	20	To check wiring				\$	30.00
To dismantle and reinstate the rear windscreen glass to the new tail gate To dismantle and transfer/refit the tail gate fittings to the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced panels \$ 200.00						<u> </u>	20
To dismantle and reinstate the rear windscreen glass 22 to the new tail gate To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced panels To go dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, \$ 1,000.00	21					Ś	80.00
To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 150.00 \$ 200.00						<u> </u>	My 05 120
To dismantle and transfer/refit the tail gate fittings to 23 the new tail gate, adjust of same To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel inner, end panel outer, including knocking, 24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 200.00	- 1	- I				Ś	150.00
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00		to the new ten bate				<u> </u>	
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	-	To dismantle and transfer/refit the tail gate fittings to					50
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	- 1					\$	120.00
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	23	the new tail gate, adjust or same	_			Ψ_	
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	- 1						
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	-	To Jahour charge for dismantle and renew the					- 41
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	- 1						1800 4days
24 straighten, repair, reshape and adjust of same. To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	- 1						, , , 3
To putty and spray painting on tail gate inner and outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 200.00	- 1					ċ	1
outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 200.00	24 s	traignten, repair, resnape and adjust of same.				Ş.	1,000.00
outer, end panel inner and outer, rear bumper, floor 25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 200.00	-		1				
25 board compartment panel. To apply rustproofing on the repaired and replaced 26 panels \$ 1,000.00	- 1						1400
To apply rustproofing on the repaired and replaced 26 panels \$ 200.00	- 1					,	
26 panels \$ 200.00 90	_					\$	1,000.00
20 pariers	T	o apply rustproofing on the repaired and replaced					No
\$ 8,132.21	26 p	anels					
					L	\$	8,132.21

AB ENGINEERING PTE LTD

Theyan Lth M 8223 5769 theyan Chhauto. 10m 1997 1700 4 clays wp

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner 10 type

Owner ID

Vehicle Details Vehicle No.

Vehicle to be Exported:

Intended Deregistration Date Vehicle Make

Vehicle Model

Primary Colour

Manufacturing Year.

Engine No.:

Chassis No.

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 01 Sep 2021

Company

082Z

GBH3434X

No

01 Sep 2021

NISSAN

NV350 PANEL VAN 2.5 5MT 5DR

Silver

2017

YD25423026A

JN1MC2E26Z0008724

\$25,062,00

02 May 2018

02 May 2018

\$1,254.00

No

\$0.00

01 May 2028

C - Goods Vehicle & Bus

\$38,303.00

\$25,535.00

\$25,535.00

OK

clp:8k

=667

64rs 9 /8/m

667×81= 54077

= 54k

59h-25535

= 28465



NV350 2,5M Used Vehicle List (12 vehicles)

Car Model

Depreciation

Eng Cap

Mileage

VIIIIdefievA

Nissan MV350 2.5N (Desc)

\$55,800

\$8,160 /yr

02-36-7018 2,488 €€ ABS BUS PTC Ltd

Available

1. Owener: Super Lam Mileage, Condition 4s Good As New, \$893.00 For 100% Finance, Easy Apply, Fast Approval, Please Contact Us For The Viewing,

Reg Date

H80 - 97224944 (M) KNOT - 92647884

Nissan NV350 2.5M (Diese)

\$56,800

\$8,100 /уг

06-Sep-2018 2,488 α

Bell KSL Auto Pte Ltd

Available

Choice Of Color Paintboork That You Like. No Repairs Needed, Lowest Price In The Market. Nice And Clean Interior. Confirmed Tip Top Condition And Reliable, 1 Owner Only! Drive Off With No Wornes! Gear...

Office No. - 62660777

Gary Tan - 96692672 | Rook Toh - 98252048 | Vincent Neo - 92393807

Nissan NV350 2.5M (Desei)

\$54,800

\$8,190 /ут

11-May-2018 2,488 cc

80,000 km Car (S) Pte Ltd

Available

100% Enhause Available! All Stock Condition. As Good As New! Exclusive Warranty Included. Trade In Welcome. Competitive Insurance Available. Contact Our Sales Consultants To Arrange For Viewing!

Office No. - 63863322

Bond - 94389996 | Leon Teo - 92329611

Nissan NV350 2.5M (Diesel)

\$59,800

\$8,300 /yr

13-Nov-2018 2,488 cc

Skylink Auto Pte Ltd

Available

1 Owner Only, 3 Month Warranty, Fully Serviced Before Handover + Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Loan Available, Trade I...

Office No. - 62665858 Skylink - 91775858

Nissan NV350 2.5M (Diesel)

\$59,800

\$8,270 /yr

23-Nov-2018 2.488 cc

Skylink Auto Pte Ltd

Available

1 Owner Only, 3 Month Warranty, Fully Serviced Before Handover + Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Loan Available, Trade I...

Office No. - 62665858

Skylinik - 91775858

Nissan NV350 2.5M (Diesel)

\$59,800

\$8,250 /yr

30-Nov-2018 2,488 cc

Skylink Auto Pte Ltd

Available

1 Owner Only, 3 Month Warranty, Fully Serviced Before Handover + Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Loan Available, Trade I...

Office No. - 62665858

Skylink - 91775858

Nissan NV350 2.5M (Diesel)

\$59,800

\$8,220 /yr

10-Dec-2018 2,488 cc

ABS Bus Pte Ltd

Available

100% Flexible And Fast Loan Approval. Trade In Vehicle Are Well Come. Monthly \$798 Only.

Office No. - 69339788

Kelly - 98818815 | KK Tang - 87760862

Nissan NV350 2.5M (Diesel)

\$57,800

\$8,460 /yr

30-Jun-2018

2,488 cc

79,000 km

AA Trust Automotive

Available

100% Loan Approval Available! 1 Owner! Full Agent Serviced! 1 More Free Servicing + Agent Warranty Package Till 100,000km. AA Trust Certified Quality Vehicle! Fully Maintained By Agent! One Of The All...

Office No. - 63450381

Dave - 98500051 | Willey - 91692071 | Amos - 84848949 | Kelvin - 96226017

Nissan NV350 2.5M (Diesel)

\$60,800

\$8,570 /yr

03-Oct-2018

2,488 cc

Auto 51 Pte Ltd

Available

Singapore Used Car Well Maintained Nissan NV350. A Van That You Should Not Miss Out With! Serve In Dual Purpose For Business Usage Or Private Usage Grab This Chance To Be The First To Assess To As

Office No. - 57351551

Grab This Chance To Be The First To Appreciate This A.

Kelvin - 91509055

2,488 CC Nissan NV350 2.5M (Diesel) 07-Dec-2018 \$60,800 \$8,360 /yr

Skylink Auto Pte Ltd

Available

1 Owner Only, 3 Month Warranty, Fully Serviced Before Handover + Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional 2 Free Servicing, Free Front Dash Camera, Free Cabin Sterilization (Fight Covid-19), Full & Flexible Local Additional Covid-19), Full & Flexible Covid-19), Covid-19), Full & Flexible Loan Available, Trade I ...

Office No. - 62665858 Skylink - 91775858

Nissan NV350 2.5M (Dresel)

\$9,070 /yr \$61,800

23-Jun-2018

2,488 cc

ABWIN (1994) Pte Ltd

Avallable

No Repairs Needed. Confirmed Tip Top Condition And Reliable, Wear And Tear Replaced. 1 Previous Owner Only! Drive Off With No Worries! Gearbox Well Service And Maintained. Trade In And High Loan Availa...

Office No. - 68416666

Jacob - 81386278 | Shawn - 91591571 | Kee Chang - 92220358 | Tony - 90065775 \$55,800

Nissan NV350 2.5M (Diesel)

\$8,180 /yr

27-Jun-2018

2,488 cc

Think One Automobile & Trading

Available

6/18 Nissan NV350 Panel Van 2.5 Manual 5 Drs, One Owner. Beautiful Brown Colour. No Repair Needed, 100% Loan.

Office No. - 68413300

Yow Tat - 91561581 | Eric - 91638879

© 2004-2021 sgCarMart. All rights reserved.

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Find the right Rental Car for you - get short term rental, long term lease, private hire cars, wedding cars to cars for p-plate probation drivers. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

SA1M218V0001 / AB Engineering Pte Ltd ENTRY DATE & TIME: 31/08/2021 13:38 (SGT) SUBMITTED BY: PAULINE KOH VERSION. 1 (31/08/2021 13:38 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be completed by the Policyholder and/or the Authorised Driver by Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability. policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any felice are a significant to the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that and that copies of this report will, for a fee, be made available upon application by Interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident**

Additional Location Information Country/State of Loss

31/08/2021 13:38 (SGT) 31/08/2021 11:46 (SGT) 58 Braddell Rd, Singapore 359905

BRADDELL ROAD TOWARDS CTE

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBH3434X

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No **Email Address** Mobile Phone No

Alternative Phone No

Yes

ABWIN LEASING PTE LTD

2XXXXX082Z

paulinekoh@abwinleasing.sg (Phone) +65-67499699 (Office) +65-67499699

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Nissan Nv350

Private hire

No - Claiming third party Commercial vehicle

Manual 2488

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number China Taiping Insurance (Singapore) Pte. Ltd.

Comprehensive

Yes

DMCVSNA00069252101

DRIVER

Name of Driver NRIC No

MURUGAN S/O M RAMU SXXXX487G



Date Of Birth

Occupation Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt, Phone Number

Email Address

Address

Address complement

Postcode Is the driver the policyholder?

If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON THE DATE OF 31 AUGUST 2021, AT ABOUT 11.46AM, I WAS DRIVING WITH VEHICLE NO: GBH3434X AND WAS TRAVELLING ALONG LEFT LANE OF BRADDELL ROAD TOWARDS CTE. THE VEHICLE INFRONT OF ME BRAKE AND STOPPED. AS SUCH, I FOLLOWED TOO AND CAME TO A STOP. A FEW SECOND LATER, A TAXI REGN NO: SHC4901M CAME AT A SPEED FROM BEHIND AND COLLIDED ONTO THE REAR OF MY VEHICLE GBH3434X. DUE TO THE GREAT IMPACT

FROM BEHIND, I FELT PAIN ON MY BACK.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

Yes No No

06/01/1977

25/04/2014

7 YEARS AND 4 MONTHS

muruganraj1977@gmall.com

BLK 230 COMPASSVALE WALK #16-424

(Phone) +65-93285740

Collision - Head to Rear

Outdoor

Male

540230

Raining

Wet

No

No

Yes

1

No

No

No

2 Yes

No Hirer

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model Vehicle Variant

Vehicle Colour

Vehicle Category Name of Driver

SHC4901M

Toyota

RedViolet

Taxi

CHOW SWEE CHUA

Accident report SA1M218V0001

NRIC No

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SXXXX984H

FRONT PORTION DAMAGED

INJURED PERSONS DETAILS

INJURED 1

Name of injured person

Gender

Phone No

Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

MURUGAN S/O M RAMU

Male

(Phone) +65-93285740

BLK230 COMPASSVALE WALK #16-424

540230

BACK PAIN GBH3434X

Yes

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Enformation provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may
- after insurance companies to repudiate policy liability. 4. The issue and acceptance of this Formby insurance companies is not an admission of policy tability on the part of the insurance соправез.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Contrelestablished by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties,
- 7. By the leagureak of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

i understand, acknowledge, agree and consent that :

- (a) Wy insurer , my w crishop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set cut in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and declase and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/flaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (# processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (or) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers law yers/law firms, may/are permitted to collect, (callectively the "Purposes") use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to free third party service providers or agents (including their tay yers/law ferrs), which may be siled outside of Singapore, for one or none of the above Purposes

Policyholder's Synaturo / Date & Trre

CO.Peg.No. m 2172707

> Driver's Signature (If priver is not the policyholder) / Dale & Time


31/03/2021

Witnessed by Reporting Centre Personnel

Sketch Plan

A. aB43434x

B. 54C 4901M



Describe (Circumstances	of the	Accident
------------	---------------	--------	----------

ON THE DATE OF 31 AUGUST 2021, AT ABOUT 11.46AM, I WAS DRIVING WITH VEHICLE NO: GBIB434X AND WAS TRAVELLING ALONG LEFT LANS OF BRADDELL ROAD TOWARDS OFF. THE VEHICLE INFRONT OF ME BRAKE AND STOPPED, AS SUCH, I FOLLOWED TOO AND CAME TO A STOP, A FEW SECOND LATER, A TAXI REGN NO: SHC4901M CAME AT A SPEED FROM BEHIND AND COLLIDED ONTO THE REAR OF MY VEHICLE GBH3434X, DUE TO THE GREAT IMPACT FROM BEHIND, I FELT PAIN ON MY BACK.

CONTRACTOR OF THE CONTRACTOR O

Declaration

W/we declare the foregoing particulars are true in every respect.

& Time

Policyhelder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel //