



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21009215/Ktf3e2 Date: 06/10/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLC 8904G
	Policy No.	Z21VP05029216	Coverage (\$)	0.00
	Claim No.	21/21/21/VP05/024914	Excess (\$)	1,000.00
	Assign From	ONG LI LI	Assign Date	01/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA GLS (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHD841CMHU195373	Colour	METALLIC DARK BLUE
	Odometer	157794 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/08/2021	Inspection Date	02/09/2021
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A) THE MARKET VALUE IS S\$51,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	