



Exceptional Journeys

Surveyor : RASUL LKK
Claim : TP CHINA TAIPING
DOA : 27.08.2021
Emailed : 11.11.2021, 5.35pm
Date Survey : 02.09.2021

VEHICLE NO : SMS 6377 U
MODEL : KIA CERATO 1.6 A EX
WIP : 38568

Material	:	\$	5,716.00
Labour	:	\$	7,750.00
Sub-Total	:	\$	13,466.00
	:	\$	-
Less Excess	:	\$	-
Total	:	\$	13,466.00
GST 7%	:	\$	942.62
Grand Total	:	\$	14,408.62
Finalise By/Date	:		LOI / 11/11/2021

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 12 WORKING DAYS + 4 Days (2) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 16

☒ TP claim YQ 4211 X

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHOON LENG ALEX	Cust No/Name	/TAN CHOON LENG ALEX
15 BEDOK RESERVOIR VIEW	Reg No/Reg Date	SMS6377U / 06/03/2020
#01-03	Date In/Mileage	14/09/2021/ 20386
SINGAPORE 478933	Chassis/Package	KNAF3416ML5069379
Contact No Mobile: 90621989	Engine No	G4FGKH755239
14/09/2021	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	11/11/2021/ 17:17	TLK	260 / AiTing	38568			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT DOOR, RH REAR DOOR, RH WING MIRROR ASSY, RH REAR FENDER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 3200.00
S SPECIALISTJOB WO:1264837, ACCIDENT TOWING FROM TAMPINESE AVE 1 TO C&C PG → Supp.								85.00
E PNT98000 RESPRAY ON RH FRONT DOOR, RH REAR DOOR, RH REAR FENDER, RH WING MIRROR COVER, RH FRONT DOOR HANDLE, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1850.00
E PNT88000 TRANSFER RH FRONT DOOR ATTACHMENTS TO NEW PANEL								✓ 160.00
E PNT88000 TRANSFER RH REAR DOOR ATTACHMENTS TO NEW PANEL								✓ 160.00
E PNT88000 REMOVE & INSTALL REAR SEATS TO FACILITATE REPAIR								✓ 150.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR								✓ 150.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST								✓ 300.00
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								✓ 150.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 120.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 280.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								✓ 180.00
M SUNDRY								✓ 50.00

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN CHOON LENG ALEX	Cust No/Name /TAN CHOON LENG ALEX
15 BEDOK RESERVOIR VIEW	Reg No/Reg Date SMS6377U / 06/03/2020
#01-03	Date In/Mileage 14/09/2021/ 20386
SINGAPORE 478933	Chassis/Package KNAF3416ML5069379
Contact No Mobile: 90621989	Engine No G4FGKH755239
14/09/2021	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	11/11/2021/ 17:17	TLK	260 / AiTing	38568			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TRANSFER RH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
M SUNDRY								85.00
SUNDRIES								✓ 480.00
S SPECIALISTJOB								120.00
DUPLICATE ONE PC OF REMOTE CONTROL KEY → Supp.								
S SPECIALISTJOB								
SUPPLY RH REAR SPORTS RIM								
S SPECIALISTJOB								
SUPPLY & INSTALL RH REAR QUARTER GLASS SOLAR FILM - RIKECOOL → Supp.								
X	MIRROR ASSY-OUTSIDE RR VIEW,RH	1.00	✓	559.00	00.00	559.00		
X	PANEL ASSY-FRONT DOOR,RH	1.00	✓	1277.00	00.00	1277.00		
X	PANEL ASSY-REAR DOOR,RH	1.00	✓	1377.00	00.00	1377.00		
X	PANEL ASSY-QUARTER OUTER,RH	1.00	✓	1349.00	00.00	1349.00		
X	MOULDING ASSY-FRT DR FRAME,RH	1.00	✓	37.00	00.00	37.00		
X	HANDLE ASSY-DOOR OUTSIDE,RH	1.00	✓	164.00	00.00	164.00		
X	PAD-FR DR O/S HDL HINGE,RH	1.00	✓	5.00	00.00	5.00		
X	PAD-FR DR O/S HDL COVER,RH	1.00	✓	5.00	00.00	5.00		
X	COVER-FR DR O/S HDL RH	1.00	✓	14.00	00.00	14.00		
X	MOULDING ASSY-RR DR FRAME,RH	1.00	✓	44.00	00.00	44.00		
X	BLACK TAPE-FR DR RR,RH	1.00	✓	13.00	00.00	13.00		
X	BLACK TAPE-RR DR FR,RH	1.00	✓	13.00	00.00	13.00		
X	BLACK TAPE-RR DR FRAME RR OTR,	1.00	✓	8.00	00.00	8.00		
X	FILM-ANTI CHIPPG RH	1.00	✓	27.00	00.00	27.00		
X	GLASS & MOULDING ASSY-QUARTER → Supp.	1.00		252.00	00.00	252.00		
X	LATCH ASSY-FRONT DOOR,RH	1.00	?	400.00	00.00	400.00		
X	BASE ASSY-FR DR O/S HANDLE RH	1.00	?	52.00	00.00	52.00		
X	PLUG-HOLE	1.00		1.00	00.00	1.00		
X	PAD-WINDSHIELD GLASS	10.00		2.00	00.00	20.00		
X	STOPPER-GLASS	2.00		4.00	00.00	8.00		
X	KEY-BLANKING PIC	1.00		15.00	00.00	15.00		
X	KEY SUB SET-DOOR,RH	1.00		75.00	00.00	75.00		
X	PLUG-HOLE	1.00		1.00	00.00	1.00		

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHOON LENG ALEX	Cust No/Name	/TAN CHOON LENG ALEX
15 BEDOK RESERVOIR VIEW	Reg No/Reg Date	SMS6377U / 06/03/2020
#01-03	Date In/Mileage	14/09/2021/ 20386
SINGAPORE 478933	Chassis/Package	KNAF3416ML5069379
Contact No Mobile: 90621989	Engine No	G4FGKH755239
14/09/2021	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	11/11/2021/ 17:17	TLK	260 / AiTing	38568

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT TP CLAIM CHINA TAI PING YQ4211X DOA : 27.08.21 SURVEYOR RASUL-LKK 02.09.21 REPAIR 12 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	5,716.00	Nett	13,466.00
Labour	6,550.00	7% GST on	13466.00
Standard Menu	0.00		
Specialist Job	770.00	Total Payable	14,408.62
Diagnostics Job	0.00		
Sundry/Others	430.00		
Total(w/o GST)	13,466.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : CHINA TAIPING

Supplementary Parts For Registration No.: SMS 6377 U

<u>Materials</u>		<u>Cost (\$)</u>
1	Glass & moulding assy-Quarter	252.00
2	Plug-hole	1.00
3	Pad-windshiled glass (x10)	20.00
4	Stopper-glass (x2)	8.00
5	Key-blanking pic	15.00
6	Key sub set-Door, RH	75.00
7	Plug-hole	1.00
Total Materials		372.00

<u>Labour</u>		<u>Cost (\$)</u>
1	Towing fee	85.00
2	Duplicate one pc of remote control key	85.00
3	Supply & install RH rear quarter glass solar film-RikeCool	120.00
Total Labour		290.00
Taxable amount		662.00
7% GST		46.34
Grand total		<u>\$ 708.34</u>

Thank You.

Yours faithfully

LOI AI TING
 SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
 DID : 6568 4556 / 6568 4501
 FAX : 6565 1240 / 6567 5258