

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Denise

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0719/2021/JT

9-Sep-21

CHANG


1 of 1

SDZ 612 A

AUDI A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	HEADLIGHT WASHER PIPE <i>ut</i>	\$ 39.00	<i>✓</i> 30.8
GRAND TOTAL		\$ 39.00	

For Premium Automobiles Pte Ltd


Authorised Signature

Adrian Ling
10/09/21
sls


Car - n

6/9/21 -

wip = 42281.

PREMIUM AUTOMOBILES

Kiam/Hong



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	\$ 1,787.00	✓
2	FRONT BUMPER FIXING PARTS see	1	TBC	X
3	FRONT BUMPER SECURING STRIP Missing	2	\$ 71.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	1	\$ 210.00	?
5	FRONT BUMPER AIR GUIDE - RH Del'd	1	\$ 63.00	✓
6	FRONT BUMPER AIR GUIDE GRILLE - RH ?	1	\$ 365.00	?
7	FRONT BUMPER GUIDE SECTION - RH Dam'd	1	\$ 38.00	✓
8	HORN - RH	1	\$ 126.00	+
9	HORN BRACKET - RH	1	\$ 29.00	✓
10	FRONT FENDER - RH Distorted	1	\$ 767.00	✓
11	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00	?
12	FRONT FENDER CLOSING ELEMENT Best	1	\$ 72.00	✓
13	FRONT FENDER TOP BRACKET - FRONT RH Best	1	\$ 35.00	✓
14	FRONT FENDER DEFORMATION BRACKET - RH Best	1	\$ 49.00	✓
15	RIVET see	6	\$ 20.00	✓
16	FRONT FENDER TOP BRACKET - REAR RH Best	1	\$ 32.00	✓
17	FRONT FENDER BRACE - RH Best	1	\$ 118.00	✓
18	FRONT WHEEL HOUSING LINER - RH Del'd	1	\$ 241.00	✓
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	TBC	?
20	FRONT WHEEL SPOILER Deformed	1	\$ 73.00	✓
SUB TOTAL SPARE PARTS		:	\$ 4,298.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL SPOILER TRIM - RH <i>cracked</i>	1	\$ 36.00	✓
22	FRONT FENDER STONE CHIP GUARD - RH <i>new</i>	1	\$ 51.00	✓
23	FRONT FENDER TOP COVER - RH <i>cracked</i>	1	\$ 31.00	✓
24	FRONT HEADLIGHT CORNER COVER - RH <i>cracked</i>	1	\$ 23.00	✓
25	BONNET <i>Dented</i>	1	\$ 3,246.00	✓
26	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 412.00	✗
27	BONNET HINGE - LH / RH <i>new</i>	2	\$ 610.00	✓
28	BONNET IMPACT PROTECTOR - LH / RH / CENTER <i>new</i>	1	\$ 84.00	✓
29	BONNET STRIKER <i>new</i>	1	\$ 50.00	+
30	BONNET LOCK	1	\$ 214.00	+
31	HEADLIGHT - RH <i>cracked</i>	1	\$ 7,693.00	✓
32	HEADLIGHT LIFT CYLINDER - RH ?	1	\$ 210.00	?
33	HEADLIGHT LIFT CYLINDER HOSE <i>new</i>	1	\$ 93.00	+
34	LOCK CARRIER <i>cracked</i>	1	\$ 1,016.00	✓
35	COOLANT <i>new</i>	6	\$ 266.00	✓
36	FRONT FENDER CONNECTING PLATE - RH ?	2	\$ 217.00	?
37	WATER RESERVOIR ?	1	\$ 251.00	?
38	FRONT WINDSCREEN <i>cracked</i>	1	\$ 147.00	1125
39	FRONT WINDSCREEN FOIL <i>new</i>	1	\$ 1,125.00	147.
40	FRONT WINDSCREEN RETAINING SPRING	1	\$ 137.00	✓
SUB-TOTAL SPARE PARTS		:	\$ 15,912.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT WINDSCREEN SPRING CLIP <i>new</i>	1	\$	21.00	✓
42	PRIMER <i>new</i>	1	\$	20.00	✓
43	FRONT DOOR - RH <i>Dented</i>	1	\$	3,192.00	✓
44	FRONT DOOR OUTER SEAL - R <i>new</i>	1	\$	205.00	✓
45	BONDING AGENT ?	1	\$	49.00	?
46	CLEANING SOLUTION	1	\$	68.00	?
47	APPLICATOR ?	1	\$	8.00	?
48	BUNGS <i>new</i>	1	\$	4.00	+
49	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1		TBC	+
50	FRONT DOOR CATCH - RH ?	1	\$	105.00	✓
51	TYRE PRESSURE STICKER <i>new</i>	1	\$	38.00	✓
52	FRONT WINDOR REGULATOR - RH	1	\$	282.00	+
53	FRONT WINDOR REGULATOR MOTOR - RH <i>new</i>	1	\$	313.00	+
54	REAR VIEW MIRROR <i>new</i>	1	\$	1,079.00	+
55	REAR VIEW MIRROR TOP COVER ?	1	\$	32.00	?
56	FRONT MIRROR MOUNTING - RH ?	1	\$	897.00	?
57	FRONT RIM - RH <i>new</i>	1	\$	1,690.00	✓
58	FRONT SUB FRAME ?	1	\$	1,891.00	?
59	FRONT WISHBOON LINK - RH <i>Best</i>	1	\$	539.00	✓
60	FRONT SUSPENSION GUIDE - RH <i>Best</i>	1	\$	943.00	✓
SUB-TOTAL SPARE PARTS		:	\$	11,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDZ 612 A

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
photo 61	FRONT UPPER ARM - RH <i>Best</i>	2 \$	1,024.00 ✓	
62	FRONT WHEEL BEARING HOUSING - RH ?	1 \$	968.00 ?	
photo 63	FRONT SWIVEL JOINT - RH <i>Best</i>	1 \$	193.00 ✓	
64	FRONT WHEEL HUB - RH ?	1 \$	479.00 ?	
photo 65	FRONT WHEEL BEARING - RH <i>Best</i>	1 \$	246.00 ✓	
66	FRONT SUSPENSION FORKS - RH <i>Best</i>	1 \$	264.00 ✓	
67	FRONT COUPLING ROD - RH <i>Best</i>	1 \$	127.00 ✓	
68	FRONT ANTI ROLL BAR ?	1 \$	433.00 ?	
69	FRONT DRIVE SHAFT - RH ?	1 \$	2,650.00 ?	
photo 70	FRONT SHOCK ABSORBER - RH <i>Best</i>	1 \$	301.00 ✓	
71	FRONT STEERING RACK ?	1 \$	6,787.00 ?	
72	FRONT TRACK ROD - RH ?	1 \$	99.00 ?	
73	FRONT TIE ROD END - RH ?	1 \$	197.00 ?	
74	FRONT LOWER NOISE INSULATION ?	1 \$	572.00 ?	
75	FRONT DOOR WINDOW CHROME SLOT SEAL - RH <i>new</i>	1 \$	307.00 ✓	
76	ACRYLIC SEALANT ?	S/N \$	180.00 ?	
77	CAVITY WAX ?	S/N \$	140.00 ?	
78	METAL FILER POWER ?	S/N \$	280.00 ?	
79	STONE CHIPS ?	S/N \$	180.00 ?	
80	FRONT WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00 ✓	
81	SUNDRIES ?	\$	500.00 ?	
TOTAL SPARE PARTS		:	\$ 47,713.00	
TOTAL LABOUR CHARGES		:	\$ 24,794.00	
GRAND TOTAL		:	\$ 72,507.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.