

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21009246/Vuce2	
	8 SHENTON WAY SINGAPORE 0688		Date:	10/09/2021		
	ATTN: PAY DANIE	<u>L</u>		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 3765G	Veh. Inspected	k	SKN 3941K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03H3C	Excess (\$)		0.00	
	Assign From	PAY DANIEL	Assign Date		02/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ CLA180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WDD1173422N076556	Colour		WHITE	
	Odometer	83453 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	CONTINENTAL		6 mm	
	L/H Front Tyre	225/40 R18	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/40 R18	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/40 R18	CONTINENTAL		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	01/09/2021	Inspect Date /	Time	02/09/2021 (05:30 PM)	
	Survey held at ALPHA CAR SERVICES PTE LTD					
	BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21009246/Vuce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser