



[Handwritten signature]

TP Budget Direct

Hui Rong

2 September 2021

Budget Direct

3rd Party Claim - Motor Claims Department

ESTIMATES FOR FJ 53 Z - YAMAHA RXZ Chassis: PMY5PV100A0034299

Ori Reg: 25JULY2011

COE Till: 24 JUL 2031

List Items

S/N	QTY	Description	Unit Price	Amount
1	2	handlebars LH & RH <i>Best</i>	100.00	\$200.00
2	2	handlebar grips LH & RH <i>Not n</i>	20.00	\$40.00
3	2	handlebar balancers LH & RH <i>21 cut</i>	25.00	\$50.00
4	2	handlebar side mirrors LH & RH <i>21 cut</i>	40.00	\$80.00
5	1	handlebar LH clutch lever <i>Not n</i>	50.00	\$50.00
6	1	handlebar RH front brake lever <i>cut</i>	50.00	\$50.00
7	1	headlamp assembly <i>crushed</i>	220.00	\$220.00
8	1	headlamp fairing <i>cut</i>	160.00	\$160.00
9	1	headlamp fairing visor <i>crushed</i>	85.00	\$85.00
10	2	front signal lamps LH & RH <i>LH crushed, RH cut</i>	60.00	\$120.00
11	1	speedometer & rpm meter <i>cut</i>	460.00	\$460.00
12	2	front forks <i>Best</i>	340.00	\$680.00
13	2	front fork stem bearings (2 sets) <i>Not n</i>	90.00	\$180.00
14	1	front fork upper bracket (triple plate) <i>Best</i>	120.00	\$120.00
15	1	front fork lower bracket (triple plate) <i>Best</i>	120.00	\$120.00
16	1	front stem stay assembly <i>Best</i>	220.00	\$220.00
17	1	front rim - chrome <i>Best</i>	350.00	\$350.00
18	1	front rim bearings (set) <i>Not n</i>	80.00	\$80.00
19	1	front rim slider (long bolt) <i>Not n</i>	40.00	\$40.00
20	1	front rim slider nut <i>cut</i>	5.00	\$5.00
21	1	fuel tank casing <i>Not n</i>	480.00	\$480.00
22	1	centre side fairings (rxz) RH <i>Not n</i>	100.00	\$100.00
23	1	rear tail fairing <i>Not n</i>	145.00	\$145.00
24	1	rear tail fairing handlebar <i>Not n</i>	70.00	\$70.00
25	1	rear tail fairing signal lamps <i>Not n</i>	60.00	\$60.00
26	1	rear tail fairing brake lamp <i>Not n</i>	80.00	\$80.00
27	1	kick-start pedal <i>Not n</i>	65.00	\$65.00
28	1	rider footrest - RH <i>Not n</i>	45.00	\$45.00
29	1	pillion footrest - RH <i>Not n</i>	45.00	\$45.00
30	1	footrest bracket assembly - RH <i>Not n</i>	165.00	\$165.00
31	1	side stand <i>Not n</i>	80.00	\$80.00
32	1	main stand <i>Not n</i>	110.00	\$110.00
33	1	exhaust assembly <i>Not n</i>	600.00	\$600.00
34	1	exhaust mid pipe - side protector <i>cut</i>	90.00	\$90.00
35	1	exhaust rear muffler - side protector cover <i>cut</i>	90.00	\$90.00
36	1	exhaust gasket <i>Not n</i>	40.00	\$40.00
37				\$0.00

Total before discount: \$5,575.00

Less 10%: -\$557.50

Sub Total: \$5,017.50

3195
2875.50



[Handwritten signature]

SPECIAL NETT ITEMS

S/N	QTY	Description	Price
1	1	handlebar RH Brembo RCS 15 brake master cylinder <i>leaking</i>	\$500.00 <i>2400</i>
2	1	handlebar RH Rizoma brake reservoir and bracket <i>new</i>	\$250.00 <i>20</i>
3	1	front number plate <i>dent</i>	\$30.00 <i>200</i>
4	1	front fender/mudguard - Aprilia RS125 <i>dent</i>	\$280.00 <i>200</i>
5	1	front tyre <i>not in</i>	\$180.00 <i>X</i>
6	1	rear suspensions - Koni brand @ \$550 each <i>new</i>	\$1,100.00 <i>X</i>
7	1	front brake disc - enlarged size <i>new</i>	\$280.00 <i>+</i>
Total:			\$2,620.00 <i>620.</i>

LABOUR & MISC. CHARGES

S/N	QTY	Description	Price
1		labour charge	\$400.00 <i>250</i>
2		spray paint and misc stickers	\$200.00 <i>180</i>
3		release & renew - brake fluid bleeding	\$100.00 <i>40</i>
4		chassis alignment - front	\$250.00 <i>X</i>
5			
6			
Total:			\$950.00 <i>470</i>

Grand Total: \$8,587.50

Lump Sum -20% : \$6,870.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/S 03/09/21

04/09/21

total: 3965.50
L/s: 3.1K.