Our Job Ref No : 305485450 Date : 08/09/21 FINALIZATION FORM					makas	ENGINEERING ComfortOnlGra Engineering Pla Ltd 59 Layeng Drive Singapore 508969 Fax: 6546 8150				
To	LKK					Fax :				
Attn	1		Т	HEVAN						
Vehic	cle Reg	No,	SHA1	049D	D	ate of Accident	:01/09/21			
The s	survey	and estima	ates of t	he repairs of the al	bove-mention	ed vehicle are i	as follows:-			
1.	The repair job shall bill to:				IIG ASIA		SLN8956Z			
2.	The f	inalized an	nount si	nall be:						
	(a)	Spare Pa	arts afte	List discount						
	(b)	Labour C	harges							
		Total for	Part-B	y-Part Repair Cos	t					
	(c.)	Total for	Lumpsu	r (if applicable) im repair cost after Repair cost	Less: 20%	-	\$6,850.00 \$6,850.00			
3.4.	Estimated normal period for repairs: 4 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days									
5.	Thank you for your assistance.					We confirm the estimates and finalized amount				
	Signature : LIM T S			Limp	_ Si	gnature :	a			
				·	_ Na	ame :	THEVAN			
	Tel : <u>6214839</u>		8	_ Da	ate :(10/9/2/				
	Fax	: <u>65</u>	546815	6	_					
For C	Official	Use Only								
		Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
1. R	ental R	ate P/Day			YES					
2. Lo	2. Loss of Income Paid				N					
3. St	ırvey F	ees			-					
5. Mo dr	4. LTA Search Fee \$7. 5. Medical Fees (on behalf of driver, if applicable)			\$7.49 /\$2.00						
6 O	verrun									
Rema	arks:									

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	Ì
		((L/S)	
			SHA1049D	P2/2	
	Front No Plate With Trim Cover			\$55.00	Cra
	Reverse Sensors			\$135.70	/Cut
	NETT TOTAL			\$190.70	
	SPARE PARTS TOTAL			\$13,527.18	
	Labour Charge				
	Panel Beating			\$1,200.00	#20 8 6 4C
	Spray Painting Charge			\$1,200.00	750
	Wiring Charge			\$50.00	30
	Tuff Kote			\$50.00	
	Towing Charge			\$60.00	
	Remove/Refix Reverse Sensor			\$120.00	30
	Remove/Refix Radiator			\$90.00	XWA
	Remove/Refix Aircon & Refill Gas			\$150.00	KNA
	TOTAL LABOUR			\$2,920.00	
	ESTIMATE TOTAL			\$16,447.18	
	This is an initial estimate based on a visual inspection of th prepared after the vehicle is surveyed by a motor Surveyed by	e above veh	icle. The final repair	quantum will be	

Theran LAH A 82235769 thwan Cliff qu to. ww 4 days up 2/9/2/ 1645 LIS after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Updated | November 2020

P1/2

DATE

MODEL

2-Sep-21

Hyundai i40

LKK-

INSURANCE AIG ASIA

VEHICLE NO : SHA1049D

MVA: NA

ART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bonnet	1		\$2,265.90
	Bonnet Hinge (LH/RH)	2	\$126.70	\$253.40 MX SUC
	Bonnet Lock	1		\$142.20 7 x SUC
	Radiator Grille H Emblem	1		\$129.50 Cut
	Radiator Grille	1		\$1,480.00/(4+
	Front Bumper	1		\$1,052.20 1066
	Front Bumper Clips	10	2.20	\$22.00 N/C
	Front Bumper Sponge	1		\$379.20 (nL
	Front Bumper Reinforcement	1		\$588.40 01
	Front Bumper Centre Grille	1		\$114.00 Lax
	Front Bumper Lip	1		\$152.00 Aug. NN
	Front Bumper Bracket Top (LH/RH)	2	\$22.40	\$44.80 \$ *SUC
	Front Bumper Bracket (LH/RH)	2	\$24.60	\$49.20 nec
	Headlamp Support Panel Assy	1		\$907.40 KSUC
	Headlamp (LH/RH)	2	\$1,388.00	\$2,776.00 RHONLYD
	Headlamp Support Top Cover	1		\$222.60 Suc
	Radiator	1		\$1,637.20 ₹ S ∪C
	Radiator Fan/Cowling	1		\$1,194.20 ^{SUC}
	Radiator Guard	1	\$76.50	\$153.00
	Horn Unit (LH/RH)	2	\$73.80	\$147.60 Suc
	Horn Wire	1		\$156 60 14
	Aircon Condenser	1		\$947.80 \$30 C
	Aircon Suction & Liquid Hose	1		\$624.00 \$ SUC
	Rear Bumper	1		\$553.00 (at
	Rear Bumper Under Cover	1		\$228.00 (at
	Rear Bumper Clips	10	\$2.20	\$22.00 nce
	Rear Bumper Reinforcement	1		\$428.40 X.Svc
	SUB TOTAL LESS 20% DISCOUNTED TOTAL			\$16,670.60
				\$3,334.12
				\$13,336.48