



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009272/Avf3n2 Date: 13/05/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 6950U	Veh. Inspected	JTU 128	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011532/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	03/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	BMW S1000RR	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WB10D8006JR926092	Colour	SILVER	
Odometer	14916 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/55 R17	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2021	Inspection Date	03/09/2021	
Survey held at	ADVANCE AUTO GARAGE 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	