



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21009276/Kuf3e2 Date: 10/12/2021 Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.		Veh. Inspected	SLW 2745H
	Policy No.	Z21VP05028531	Coverage (\$)	0.00
	Claim No.	21/21/21/VP05/024920	Excess (\$)	4,500.00
	Assign From	GERALD POH	Assign Date	03/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA JAZZ (A)	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JHMGK5850JX203974	Colour	METALLIC DARK BLUE
	Odometer	36332 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm
	L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/09/2021	Inspection Date	03/09/2021
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$59,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	