

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Joshua Ng
Blk508B Yishun Avenue 4
#13-62

Singapore 762508

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Joshua Ng

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 02/09/2021
WIP No. . : 43900
Veh.In/Out: 01/09/2021
*Tel.No. . : Mobile: 94793995
Reg.No. . : SMK181Z
Reg.date . : 28/07/2017
Mileage .. : 0
Chassis No: YV1LF10ACH1187723

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, FRT GRILL, FRT LOWER SPOILER, ETC	0	1700.00	0		1,700.00 S	850
800	TO PUTTY SPRAY PAINT ON FRT BUMPER, ETC	0	1700.00	0		1,700.00 S	1125
R06	TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00 S	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	510.00	0		510.00 S	
	VO39841726/BUMPER CO <i>sea</i>	1.0 EA	2670.30			2,670.30 S	2403.27
	BUMPER SPOILER CTR X <i>sea</i>	1.0 EA	323.10			323.10 S	290.79
	BUMPER SPOILER FRT L <i>sea</i>	1.0 EA	323.10			323.10 S	290.79
	BUMPER SPOILER FRT R <i>sea</i>	1.0 EA	323.10			323.10 S	
	BUMPER BRACKET FRT L <i>sea</i>	1.0 EA	91.60			91.60 S	
	BUMPER BRACKET FRT R <i>sea</i>	1.0 EA	91.60			91.60 S	
	BUMPER BRACKET FRT L <i>sea</i>	1.0 EA	91.60			91.60 S	
	BUMPER BRACKET FRT R <i>sea</i>	1.0 EA	91.60			91.60 S	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Joshua Ng
 Blk508B Yishun Avenue 4
 #13-62
 Singapore 762508

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date. : 02/09/2021
 WIP No. : 43900
 Veh.In/Out: 01/09/2021
 *Tel.No. : Mobile: 94793995
 Reg.No. : SMK181Z
 Reg.date. : 28/07/2017
 Mileage : 0
 Chassis No: YV1LP10ACH1187723

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Joshua Ng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	RADIATOR GRILLE T5 X <i>cm</i>	1.0 EA	1260.10			1,260.10	S 1134.09
	BUMPER GRILLE LH CHR <i>neu</i>	1.0 EA	366.70			366.70	S 330.03
	BUMPER GRILLE RH CHR <i>neu</i>	1.0 EA	366.70			366.70	S 330.03
	NUMBER PLATE RETAINE <i>cut</i>	1.0 EA	63.30			63.30	S 56.97
	WIPER GRILLE CLIP XC <i>neu</i>	10.0 EA	8.30			83.00	S 74.70
	BUMPER GRILLE LOWER <i>scr</i>	1.0 EA	231.70			231.70	S 208.53
	PROTECTING PLATE FRT <i>scr</i>	1.0 EA	742.90			742.90	S 667.61
	BUMPER RAIL FRT XC90 <i>? x su</i>	1.0 EA	1544.30			1,544.30	S x neu
	BLIND RIVET 4.0*21 <i>pa</i>	10.0 EA	4.10			41.00	S 36.90
	BUMPER CLIP 8x8,5 <i>m</i>	10.0 EA	6.80			68.00	S 61.20
	BUMPER INSTALLING MT <i>m</i>	1.0 EA	96.50			96.50	S 86.85
	D ADHESIVE CHEMICA <i>m</i>	1.0 EA	797.60			797.60	S 717.84
	EXPANDING NUT XC40 1 <i>us</i>	10.0 EA	6.30			63.00	S 56.70

Comprehensive Part only TP only
 Yes No

Labour Total 3,970.00
 Parts Total 9,730.80
 Package Total 0.00

Gross Total. 13,700.80
 Net..... 13,700.80
 GST @ 7.0% 959.06
 Total..... 14,659.85
 Paid..... 0.00
 Please Pay.. 14,659.85

Paul
Hp 9001268
3 days
18/09/21 @ 1130
Rozy before part

GST: S=StdRated; O=OutOfScope; Z=ZeroRated