

SUPPLEMENTARY BILL FOR CB7198X DOA 20/08/2021

PARTS	DESCRIPTION	QUANTITY	ESTIMATE
1	PISTON SET ✓ DM	4	
2	PISTON PIN ✓ DM	1	
3	PISTON SUB-ASSY ✓ DM	1	
4	RELAY ASSY, DOOR CONTROL ✓ DM	1	
5	ECU ✓ DM	1	
6	ABS X NN	1	
7	CLUTCH ASSY X NN	1	-
8	REAR BRAKE SHOE ASSY X NN	1	
9	PUMP ASSY, WATER X NN	1	
10	THERMOSTAT ?	1	
11	THERMOSTAT O-RING ?	1	
12	DISC ASSY, CLUTCH X NN	1	
13	COVER ASSY, CLUTCH 12" X NN	1	
14	BEARING, CLUTCH X NN	1	
15	BEARING, CONNECTING ROD X NN	1	
16	BEARING SET X NN	1	
17	FRONT ENGINE MOUNTING X NN	2	
18	HOSE, WATER BY-PASS X NN	1	
19	LINER CYL S/S ✓ DM	4	
20	GASKET KIT ENGINE ✓ DM	1	
21	12V FLASHER UNIT ✓ DM	1	
22	BRAKE CUP 1 1/8 X NN	8	
23	WHEEL HUB SEAL INNER X NN	2	
24	RR HUB SEAL OUTER X NN	2	
25	CLIP X NN	2	
26	GEAR OIL ✓ NEC	1	
27	Fuel Filter X NN		
28	Timing Belt X NN		
29	Pully X NN		
30	Filter ✓ DM		
SUB TOTAL FOR PARTS			-

LABOUR

1	LABOUR FOR MECHANICAL	6,400.00	1350
2	LABOUR & MATERIAL FLOORBOARD - subject to wood is damaged	5,400.00	2700
3	LABOUR FOR CLEANING	1,280.00	450
4	SUB TOTAL FOR LABOUR	13,080.00	

TOTAL ESTIMATE BILL**13,080.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

6 Days