

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2106252

64 CECIL STREET INV Date 07/09/2021

#05-02 IOB BUILDING Reference CS3/GRB21009280/R1tf3e2 SINGAPORE 049711 CDD CRP

Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SJF 1474J

Insured Veh. SLS 2588R

Claim No.

Policy No.

Accident Date 02/09/2021

Inspection Date 03/09/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 03.09.2021 03.34pm	
- Dismantle Inspection 06.09.2021 10.55am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM