

SJE :

Date of Survey :

Contacts :

Vehicle Nos : SNA 9642U

Model : BMW 116D DSR LED

Year :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2016

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear door R/H DD✓	1	\$ 1,650.95	\$ 1380.20 1,650.95
2	Rear door hinge R/H BT✓	2	\$ 115.00 227.80	\$ 230.00 455.60
3	Rear door board R/H BR✓	1	\$ 437.50	\$ ✓ 437.50
4	Rear glass R/H BR✓	1	\$ 258.30	\$ ✓ 258.30
5	Rear door outer moulding R/H BT✓	1	\$ 153.30	\$ ✓ 153.30
6	Rear pillar R/H NDX	1	\$ 883.50	\$ 883.00
7	Rear bumper CUTV	1	\$ 1,424.45	\$ 1220.30 1,424.45
8	Rear bumper reinforcement NDX	1	\$ 878.55	\$ 878.55
9	Rear bumper side bracker R/H NECV	1	\$ 151.85	\$ ✓ 151.85
10	Rear clomh NDX	2	\$ 113.50	\$ 227.00
11	Rear door handle DDV	1	\$ 166.10	\$ ✓ 166.10
12	Rear fender R/H DDV	1	\$ 786.20	\$ ✓ 786.20
13	Rear fender support bracket R/H NNX	1	\$ 161.35	\$ 161.35
14	Rear fender cowling R/H NNX	1	\$ 216.60	\$ 216.60
15	Rocker panel RH CUTV	1	\$ 407.25	\$ ✓ 407.25
16	Rear knuckle arm RH DDV	1	\$ 594.10	\$ ✓ 594.10
17	Rear shock absorber RH BTV	1	\$ 610.90	\$ 386.70 610.90
18	Rear steering rack and pinion NSX	1	\$ 3,286.25	\$ 3,286.25
19	Rear regulator BT✓	1	\$ 329.40	\$ 253.95 329.40
20	Rear regulator motor SCV	1	\$ 583.80	\$ 323.80 583.80
21	Tail lamp R/H NDX	1	\$ 840.35	\$ 840.35
22	Tail lamp bracker R/H NDX	1	\$ 112.65	\$ 112.65
			Parts Sub Total :	\$ 14,615.45
			PARTS TOTAL :	\$ 14,615.45

@ 50%

 6749.55
 337.49
 6412.07

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear bumper clips NECV	10	\$ 5.00	\$ 30.00 50.00
2	Rear fender cowling clips NNX	8	\$ 5.00	\$ 40.00
3	Wheel rim front R/H To provide invoice BR✓	1	\$ 1,526.00	\$ * * xnn 1,526.00
4	Front wheel R/H NDX	1	\$ 426.00	\$ 426.00
SPECIAL NETT TOTAL :				\$ 30.00 2,042.00

Nos.	LABOUR	S\$
1	Labour accident affected area	\$ 800.00 1,600.00
2	Spray painting	\$ 600.00 1,500.00
3	Check alignment	\$ 60.00 200.00
4	Realign rear wheel	\$ 40.00 100.00
LABOUR TOTAL :		\$ 1500.00 3,400.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey Resurvey
 6/9/2021 8/9/2021
 Titim Wu Titim Wu
 1340 hrs 1630 hrs
 Lump sum repair
 Repair days

LS 6350.00

* Invoice must be provided
 before COR offered can be amended.

PARTS TOTAL : \$ 6412.07 14,615.45
 SPECIAL NETT TOTAL : \$ 30.00 2,042.00
 LABOUR TOTAL : \$ 1500.00 3,400.00
 TOTAL : \$ 7942.07 20,057.45
 Deduct 20% : \$ 1588.41 4,011.49
 GRAND TOTAL : \$ 6353.66 15,083.40