


Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: First Capital Insurance Ltd
Date: 02/09/2021
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLH6863C
CHASSIS NO: RU3124690
MAKE / MODEL: Honda Vezel 1.5X Hybrid CVT
DATE OF ACCIDENT: 02/09/2021
YOUR INSURED VEHICLE NUMBER: SG5705E
MILEAGE: 97888 km



	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/L fender <i>X Repair</i>	1PC	\$ 1,500.00	\$ 1,500.00
2	Rear bumper <i>- 722 Cut</i>	1PC	\$ 955.00	\$ 955.00 745
3	R/L side bumper <i>- TN</i>	1PC	\$ 300.00	\$ 300.00 195
4	R/L fender wheel arch moulding <i>- Cut</i>	1PC	\$ 300.00	\$ 300.00 175.2
LIST TOTAL S\$:				\$ 3,055.00
20.00% DISCOUNT S\$:				\$ 611.00
Total				\$ 2,444.00

<u>SPECIAL NETT</u>			
1	Rear bumper clips <i>- MCC</i>	1 SET	\$ 80.00 30
Total			\$ 80.00

<u>LABOUR CHARGES</u>			
1	To labour charge for removing R/L fender, rear bumper, out to facilitate repairs and replacement of damaged parts. Also include cutting out and welding of replacement spare tyre panel	\$	1,000.00 500
2	To respray rear tailgate, end panel and spare tyre panel	\$	800.00 500
LABOUR TOTAL S\$:		\$	1,800.00
TOTAL S\$:		\$	4,324.00
7% GST		\$	302.68
GRAND TOTAL S\$:		\$	4,626.68

*4 Days.
L/S*

After repair photos.

Once Q: ang - 82880282

03/9/21

Quo Q: ang @lkkauto.com