

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6515 6888 / 9847 8613(HELPLINE)
EMAIL : enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg

**QUOTATION****M/S : JERRY TAN EYE SURGERY PTE LTD**

1 Scotts Rd,
#21-03 Shaw Centre,
SINGAPORE 228208

TEL: 67388122
67388122-MRS TAN

ATTN: COLIN H/P: 90140743

NO: WQT0801176**DATE: 01 Sep 2021****A/C CODE: C006220****TERMS: COD****YOUR REF: EV822U****VEH REG NO: EV822U**

**MAKE/MODEL: TOYOTA ESTIMA
WELCAB 3.5G 7
SEATERS**

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE. DOA: 28/08/2021 @1400 HRS ACCIDENT INVOLVING: EV822U & SLL8925Z CLAIM TYPE: 3RD PARTY CLAIM AGAINST SLL8925Z				
1 FRONT BUMPER	1 PC	682.80		682.80
2 FRONT BUMPER SIDE RETAINER RH & LH	2 PC	114.70		229.40
3 FRONT BUMPER CLIPS	10 PC	3.50		35.00
4 FRONT FENDER SHIELD RH	1 PC	351.20		351.20
5 FRONT BUMPER SPONGE	1 PC	120.00		120.00
6 TO CUT, WELD & STRAIGHTEN FRONT PORTION CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	1 SVC	500.00		500.00
7 TO FOCUS HEADLAMP, CHECK WIRING	1 SVC	30.00		30.00
8 TO SPRAY PAINT ON REPAIRED AREAS.	1 SVC	500.00		500.00
9 COMPUTERISED WHEEL ALIGNMENT	1 SVC	60.00		60.00
Total				S\$ 2,508.40
Add GST @ 7%				175.59
Grand Total				S\$ 2,683.99

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED EIGHTY THREE AND CENTS NINETY NINE ONLY

JERRY TAN EYE SURGERY PTE LTD**For RICARDO AUTO CENTRE PTE LTD**

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE