RICARDO AUTO CENTRE PTE LTD

90140743

GST: M2-0053787-4 RCB NO: 198102182M 160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722 LindAII, : enquiry@ricardo.com.sg WEBSITE: http://www.ricardo.com.sg



QUOTATION M/S: JERRY TANKEYE SURGERY PTE LTD WQT0801176 NO: DATE: 01 Sep 2021 Not boshoon !! Say & Paing 1 Scotts Rd, A/C CODE: C006220 #21-03 Shaw Centre, TERMS: COD SINGAPORE 228208 YOUR REF: EV822U TEL: 67388122 VEH REG NO: EV822U 67388122-MRS TAN ATTN: COLIN H/P:

MAKE/MODEL: TOYOTA ESTIMA WELCAB 3.5G 7

SEATERS

SALESMAN:

		DI LEEDIVII II V	•			
CCIDENT INVOLVING: EV82211 & SLI 80257					PAGE:1	
		Quantity	Unit Price	%	Amount	
WE SUBMIT HEREWITH OUR ESTIMATED COST DOA: 28/08/2021 @1400 HRS ACCIDENT INVOLVING: EV822U & SLI 89257		R TO ABOVE M	<u>s\$</u> IENTIONED	VEHICL	<u>\$\$</u> E.	
CLAIM TYPE: 3RD PARTY CLAIM AGAINST SLL	89257.					
FRONT BUMPER FRONT BUMPER SIDE RETAINER RH & LH	123 1,236	1 PC 2 PC	682.80 114.70	In	682.80	
FRONT BUMPER CLIPS FRONT FENDER SHIELD RH	258	10 PC	3.50 351.20		229.40 35.00 351.20	
FRONT BUMPER SPONGE TO CUT, WELD & STRAIGHTEN FRONT PORTION CAUSED BY ACCIDENT. ADJUST & REPLACE DA	N MAGE	1 PC 1 SVC	120.00 500.00	In	120.00 500.00	
PARTS. TO FOCUS HEADLAMP, CHECK WIRING	LWINGE				200	
TO SPRAY PAINT ON REPAIRED AREAS.		1 SVC 1 SVC	30.00 500.00		30.00 £	
COMPUTERISED WHEEL ALIGNMENT		1 SVC	60.00	nn	60.00	
			Total	S\$ 2	,508.40	
		Add (Add GST @ 7% Grand Total		175.59	
		G			,683.99	

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED EIGHTY THREE AND CENTS NINETY NINE ONLY

JERRY TAN EYE SURGERY PTE

LKK Auto Consultants hence notify

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company HDRISED SIGNATURE

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

Acknowledged by Repairer Signature:

Date:

Scanned with CamScanner