

part	LABOUR		s/n	CHECK	SGS 4242J
863	1350			135	TOTAL
517	2450			22	
18	100			60	12502.00
18	50			13	
48	40			510	0
6	80			25	
97	30			135	
168	120			22	LUMP SUM
510	120			60	
25	20			13	
550	450			36	
50				24	TOTAL suppl
980				76	
68				40	
133				41	
36				183	
622				58	
164				147	supp LABOUR
30				58	
30				173	
1948				19	
350				861	
52				1020	
409				18	
				20	0
7692	4810		0	3769	
0			0	0	