



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD			Ref:	CS3/SMR21007795/T1uf3e2-1
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	21/09/2021
			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 5158J	Veh. Inspected	SJF 23J
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/07/21/5030	Excess (\$)	0.00
	Assign From	KAREN CHAN	Assign Date	06/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. M3 COUPE	c.c	3999
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WBSKG92080E997685	Colour	BLUE
	Odometer	93649 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	285/30 R20	MICHELIN	6 mm
	L/H Front Tyre	285/30 R20	MICHELIN	6 mm
	R/H Rear Tyre	285/30 R20	MICHELIN	6 mm
	L/H Rear Tyre	285/30 R20	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/07/2021	Inspection Date	21/07/2021
	Survey held at	2 Kaki Bukit Ave 2 #01-33		
	Repairer	AUTO ASSIST SG		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	