

**Trident Auto Service Centre Pte Ltd**

8 Kaki Bukit Ave 4, #02-44

Premier @ Kaki Bukit (Gate 1)

Singapore 415875

Tel: 63441918

Date : 03/09/2021

Vehicle : SMH3775G

Make/Model : Toyota NOAH

ORD : 2018

Chassis : ZWR800345375

ODO :

ACC Date : 27/08/2021

**MS FIRST CAPITAL INSURANCE LIMITED**

6 Raffles Quay

Singapore 048580

**Estimate**

S/N	Qty	Description & Specification	Amount S\$
<u>List Items</u>			
1	1	W/mirror RH <del>CPA</del> X NN	\$1,239.40
2	1	W/mirror cover <del>BR</del> X NN	\$107.00
3	1	W/ mirror signal light <del>CPA</del> X NN	\$119.00
Total			\$1,465.40
Less 25%			\$366.35
List Total			\$1,099.05
<u>Labour</u>			
1		To replace w/mirror RH	\$200.00 100
		to repair and re-align on all accident affected areas	
2		To putty and respray on accident portion	\$200.00 100
3		To check wiring	\$60.00 20
Labour Total			\$460.00
Grand Total			\$1,559.05

Trident Auto Service Centre Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Day.

P/P

After repair photos.

Gino Qian.

8288 0282

8/9/2021