

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS/SMR21009334/Uuf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	28/09/2021	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 4997L	Veh. Inspected	ŀ	GBC 9488C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/08/21/2069	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		06/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	FIAT DOBLO CARGO (M)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	ZFA26300006141962	Colour		WHITE	
	Odometer	169234 KM	Steering		AFFECTED	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/60 R16	LASSA		6 mm	
	L/H Front Tyre	195/60 R16	LASSA		6 mm	
	R/H Rear Tyre	195/60 R16	LASSA		6 mm	
	L/H Rear Tyre	195/60 R16	LASSA		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/08/2021	Inspection Dat	e	06/09/2021	
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP				
		1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		5 Worki	ng Days	
	-					