



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21009338/Ktf3e2	
			Date: 04/10/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3902T		Veh. Inspected	SLH 4303R
Policy No.			Coverage (\$)	0.00
Claim No.	21/21/21/VC00/024922		Excess (\$)	0.00
Assign From	GERALD POH		Assign Date	06/09/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	JHMRU1830GX200855		Colour	METALLIC BLUE
Odometer	97069 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		215/60 R16	DUNLOP	3 mm
L/H Front Tyre		215/60 R16	DUNLOP	3 mm
R/H Rear Tyre		215/60 R16	DUNLOP	3 mm
L/H Rear Tyre		215/60 R16	DUNLOP	3 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2021		Inspection Date	07/09/2021
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	