

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref: CS/ICS21009339/Gvf3		
10 EUNOS ROAD 8		Date: 06/09/2021		
SINGAPORE POST CENTRE #09-04A				
SINGAPORE 408600		Code: ICS		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SCY 59P	
Policy No.	MPC21D00001800	Coverage (\$)	0.00	
Claim No.	DMPC2100301H	Excess (\$)	0.00	
Assign From	MERIMEN (LIU CHUN CHEONG)	Assign Date	06/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/09/2021	Inspection Date	07/09/2021	
Survey held at	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				