



Co. & G.S.T. Reg no. 201605297G
 Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933
 Email: automim.cilm@gmail.com Tel: 9119 8371
 Website: www.aimgarage.com.sg

C/S \$20,000

Our Ref.: AC2021066/OD

Vehicle number: SCY59P

Vehicle Made & Model: Honda Civic Type R

S/N	Qty	List Items	List Price S\$
			1,451.80 X
1	1	THROTTLE BODY X SVC	591.60 ✓
2	4	SPARK PLUG COIL @ 147.90 ✓ Contaminate	193.20 ✓
3	4	SPARK PLUG @ 48.30 ✓ Contaminate	900 1,992.50 ✓
4	1	ALTERNATOR ASSY CON DM	900 1,172.90 ✓
5	1	STARTER ASSY / CON DM	253.10 ✓
6	1	ROCKER COVER GASKET ✓ Contaminate	3800 4,083.90 ✓
7	1	ENGINE HEAD ASSY ✓ Contaminate	130.00 ✓
8	1	ENGINE HEAD GASKET ✓ Contaminate	833.80 X
9	1	ENGINE INTAKE CAMSHAFT X ^ ^	225.30 X
10	1	ENGINE INTAKE CAMSHAFT SPROCKET X ^ ^	833.80 X
11	1	ENGINE EXHAUST CAMSHAFT X ^ ^	136.80 X
12	1	ENGINE EXHAUST CAMSHAFT SPROCKET X ^ ^	213.90 ✓
13	1	ENGINE TIMING CHAIN COVER WITH GASKET ✓ Contaminate	298.40 ✓
14	8	INTAKE VALVE @ 37.30 ✓ CON	464.00 ✓
15	8	EXHAUST VALVE @ 58 ✓ CON	3,691.20 ✓
16	8	ROCKER ARM @ 461.40 ✓ CON DM	32.20 ✓
17	1	ENGINE OIL FILTER ✓ Contaminate	820.60 ✓
18	1	ENGINE OIL COOLER CON ✓ DM	4.50 ✓
19	1	ENGINE OIL COOLER GASKET ✓ Contaminate	434.10 ✓
20	1	ENGINE OIL PUMP ASSY ✓ Contaminate	4,643.40 X
21	1	ENGINE BLOCK ASSY X REPAIR	24.10 ✓
22	1	ENGINE CRANKSHAFT GASKET ✓ Contaminate	263.40 X
23	1	ENGINE COOLANT PUMP WITH GASKET ASSY X ^ ^	78.00 ✓
24	1	ENGINE THERMOSTAT ✓ Contaminate	1,602.60 ✓
25	1	ENGINE CRANKSHAFT ✓ BR	101.50 ✓
26	5	ENGINE CRANKSHAFT BEARING UPP @ 20.30 ✓ NEC	142.00 ✓
27	5	ENGINE CRANKSHAFT BEARING LOW @ 28.40 ✓ NEC	22.60 ✓
28	2	ENGINE CRANKSHAFT WASHER @ 11.30 ✓ NEC	290.80 ✓
29	4	ENGINE PISTON RING @ 72.70 ✓ NEC	480.40 ✓
30	4	ENGINE PISTON @ 120.10 ✓ BT	804.00 ✓
31	4	ENGINE PISTON CON ROD @ 201 ✓ BT	148.00 ✓
32	8	ENGINE PISTON CON ROD BEARING @ 18.50 ✓ BT	450.50 ✓
33	1	ENGINE HEAD GASKET SET ✓ Contaminate	58.10 ✓
34	1	ENGINE BLOCK GASKET SET ✓ Contaminate	

Our Ref.: AC2021066/OD

Vehicle number: SCY59P

Vehicle Made & Model: Honda Civic Type R

35	1 ENGINE INTAKE AIR FILTER	✓ Contaminate	86.00	✓
36	1 FUEL CANISTER ASSY	✓ CON	201.60	✓
37	1 ENGINE CONTROL UNIT	✓ Contaminate	1800 2,455.20	✓
38	1 ENGINE RELAY BOX ASSY	✓ Contaminate	283.60	✓

13726.3 Sub-total 29,993.40
 Plus 10% 2,999.34
 32,992.74
 15098.93

Labour Charges

39	To perform full engine overhaul		2,000.00	✓
40	To conduct dianogsis reset on faulty code		800.00	400
41	Remove & refix seat cushion, upholstery, interior trimming, etc for dry up		800.00	400
			2000	
42	4L ENGINE OIL	✓ NEC	55.25	118.80 SOZ
43	4L AUTO TRANSMISSION FLUID	✓ NEC	45.20	90.40 SOZ
44	4L BRAKE FLUID	✓ NEC	19.95	39.90 SOZ
45	4L ENGINE COOLANT	✓ NEC 11		64.60 X
46	1L POWER STEERING FLUID	✓ NEC	9.75	19.50 SOZ
47	4 GASKET GUM	✓ NEC	50	58.80 ✓

Total Labour & Misc 3,992.00 392

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 36,984.74

~~17100.00~~

~~20% 111~~

Total amount subject to part price correct.

Total amount subject to insurance approval.

LXX Auto Consultants hence notify
 the Repairer of the following:

- To receive before/after spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications to be allowed
- Supplementary items must be re-approved and
 is subject to final approval from Insurance Company

Authorised by Repairer
 Signature:
 Date:

12 days 70 days

9-2054
 102
 9-22570.90
 S.N-184.15
 2-3820
 26578.05



Co. & G.S.T. Reg no. 201605297G
 Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933
 Email: automim.claim@gmail.com Tel: 9119 8371
 Website: www.aimgarage.com.sg

Our Ref.: AC202166/OD

Vehicle number: SCY59P

Vehicle Made & Model: HONDA CIVIC TYPE R

<u>S/N</u>	<u>Qty</u>	<u>SUPPLEMENTARY</u>	<u>List Price S\$</u>
1	2	FRONT DOOR SPEAKERS @ \$150 <i>CON</i>	300.00 ✓
2	1	AIRCON FAN MOTOR <i>CON</i>	225.00 ✓
3	1	RADIATOR FAN MOTOR <i>CON</i>	250.00 ✓
4	1	AIRCON COOLING COIL <i>CON</i>	480.00 ✓
<i>cost plus 10%</i>			
Total			1,255.00

LABOUR

TO REMOVE & REFIX ENGINE GEARBOX ETCS	400.00	<i>380</i>
TO REMOVE & REFIX FRONT UNDERCARRIAGE	380.00	<i>300</i>
TO CONDUCT WHEEL ALIGNMENT	80.00	<i>60</i>
TO REMOVE & SERVICE AIRCON BLOWER, REFILL AIRCON GAS	250.00	<i>180</i>
TO REMOVE & SERVICE EXHAUST SYSTEM	100.00	✓
TOTAL	1,210.00	

ESTIMATE PARTS & LABOUR GRAND TOTAL \$ ~~2,465.00~~ 2590.50