



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YU DOMINIC YISHAN			Ref: CS/ASM21009350/Bvce2 Date: 12/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7142C	Veh. Inspected	SDV 6668X	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03H8B	Excess (\$)	0.00	
Assign From	YU DOMINIC YISHAN	Assign Date	06/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE BOXSTER	c.c	3387	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WPOZZZ98Z7U721754	Colour	GREY / BLACK	
Odometer	40377 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	POOR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	MICHELIN	6 mm	
L/H Front Tyre	235/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	265/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	265/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2021	Inspection Date	07/09/2021	
Survey held at	A T PERFORMANCE 160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			24 Working Days	