



Claim	S1M03H8B
Reference	CS/ASM21009350/Bvce2 
Loss Date	2 September 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	5 Sep 2021 8:17:00 AM
Request Date	7 September 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SDV6668X
Vehicle	
Registration #	
Make	TPVD Porsche
Model	BOXSTERS 987

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

- Messages2
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2202724.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022
	Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022	
	Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022	
	LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2022	
	TP LOD.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	10 May 2022	
	SDV 6668X RES 2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2021	
	SDV 6668X RES 1_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	24 November 2021	

