



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Ref: CS/AWA21009351/R1uf3e2

Date: 18/10/2021

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1046S	Veh. Inspected	YN 7655U
Policy No.	BVFCB0013842100	Coverage (\$)	0.00
Claim No.	NSV2100118/HLF	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	06/09/2021

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI CANTER FEB21ER	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	FEB21EA00890	Colour	WHITE
Odometer	289577 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R15	BRIDGESTONE	7 mm
L/H Front Tyre	195/85 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/08/2021	Inspection Date	07/09/2021
Survey held at	566 woodlands road (mandai estate) s728697		
Repairer	CONNECT3		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------