

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Seng Kok Cheng  
61 Tampines Central 7  
#10-21 Singapore 528595

Vehicle No : SMU 1695 Z  
Make : Toyota C-HR  
Year : 2019

*Not Authorized  
11 days @ 2250k  
Paying After Posing  
3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy		R \$1,150.70 X
1 pc			na
1 pc			na
2 pcs		\$612.40	na
1 pc			na
1 pc			na
1 pc	Rear tail-gate emblem - Hybrid		na \$48.90 X
1 pc	Rear tail-gate emblem - C-HR		na \$45.80 X
1 pc	Rear tail-gate emblem		na \$62.30 X
1 pc	Rear boot rubber		na \$205.60 X
1 pc	Rear bumper		na \$885.70
1 pc	Rear bumper reinforcement	393.20	na \$483.20
2 pcs	Rear bumper reflector garnish		\$125.60 na \$251.20 X
1 pc	Rear lower bumper	465	CM \$485.70
2 pcs	Rear bumper side retainer		\$75.10 na \$150.20 X
1 pc	Rear buzzer		CM \$175.20
2 pcs	Rear fender arch garnish		\$165.20 na \$330.40 X
1 pc	Rear end panel		na \$725.70 X
1 pc	Rear end panel inner garnish		na \$402.10 X
			\$8,547.18
			Less 25 %
			\$2,136.79
			\$6,410.38

*Rear bumper lower cover CM 85.70 ✓  
Towing cover 45.80 od ✓ 29*

## S Nett

15 pcs	Rear bumper clip
1 pc	Rear reverse sensor
1 pc	Rear windscreen sealant
1 pc	Rear no plate

\$2.00	na	\$30.00	✓
Short / Red	na	\$200.00	✓
	na	\$40.00	X
	na	\$35.00	X
balance c/f		\$6,715.38	

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

ASS. REQ. BY:

REF: *LPC 1 0*

*1695 Z*

balance b/f \$6,715.38

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,000.00 *300/*

To putty & spray paint on accident affected portion

\$1,000.00 *600/*

Check and reconnect wiring

\$40.00 *152*

To anit- rust proofing

*nn* \$100.00 *X*

Remove/refit rear windscreen

*nn* \$120.00 *X*

Remove/refit rear boot upholstery

*nn* \$120.00 *X*

Total \$9,095.38