

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/4

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Mr
LIM
TIONG GUAN
635A PUNGGOL DRIVE
#08-617
Singapore 821635

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

06-09-2021
5211043801
30001
2021033698/ 1
04-09-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLB1020H	5G12BZ	28-03-2016	WVWZZZAUZGW053450	Golf 1.2 TLBM 81 TSI D7F	44,013

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	R&R ROOFLINING				#1	1,520.00	2,696.40
9801B001	R&R FRT SEAT BELT & AIRBAG CONTROL UNIT				#1	1,680.00	1,797.60
9801B001	R&R REAR AXLE BEAM				#1	3,360.00	3,595.20
9801B001	R&R WHEEL BEARING				#1	840.00	898.80
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R TYRE & BALANCE				#1	50.00	53.50
5G4867501P ZA4	Moulded Headlining Pearl ROOFLINING	1	pcs.	1,092.49	#1	1,092.49	1,168.96
5G0867633	Clamp	4	pcs.	1.28	#1	5.12	5.48
5G4880742E	Head Airbag Unit	1	pcs.	1,518.87	#1	1,518.87	1,625.19
5G0857607B Y20	SIDE CURTAIN AIRBAG RH	1	NEC	96.72	#1	96.72	103.49
5G0857643B Y20	Grab Handle Folding Pearl	1	NEC	101.32	#1	101.32	108.41
5G0853437 Y20	RHS ROOF TOP HANDLE FRT	2	pcs.	16.34	#1	32.68	34.97
5G4867292F 82V	Roof Grab Handle Pearl Gr	1	pcs.	179.74	#1	179.74	192.32
5G4853372C 82V	RHS ROOF TOP HANDLE REAR	1	NEC	71.17	#1	71.17	76.15
5G4857705B RAA	Trim With Emblem Pearl Gr	1	NEC	71.17	#1	71.17	76.15
5G4857706B RAA	Lining Pillar B Titanium	1	NEC	71.17	#1	71.17	76.15
WHT003682	RHS B-PILLAR TRIM (LOWER)	1	NEC	71.17	#1	71.17	76.15
N 98924301	Scuff Plate Sill Panel Ti	1	NEC	71.17	#1	71.17	76.15
N 98926001	RHS INNER SCUFF PLATE	1	NEC	71.17	#1	71.17	76.15
8V0857819	Three-Point Automatic Sea	1	NEC	71.17	#1	71.17	76.15
N 10572403	LHS FRT SEAT BELT	1	NEC	71.17	#1	71.17	76.15
5G4881806DJNQI	Three-Point Automatic Sea	1	NEC	71.17	#1	71.17	76.15
5G4881776AK	RHS FRT SEAT BELT	1	NEC	71.17	#1	71.17	76.15
5G0880242C	Bolt With Polygon Socket	2	pcs.	6.61	#1	13.22	14.15
5G0959655D Z00	Socket Hd. Screw With Pol	2	pcs.	6.70	#1	13.40	14.34
5Q0959354A	Socket Hd. Screw With Pol	2	pcs.	6.61	#1	13.22	14.15
5G0821106A	Seat Belt Height Adjuster	1	NEC	115.21	#1	230.42	246.55
N 90817302	Bolt	2	pcs.	3.99	#1	7.98	8.54
	Backrest Cover	1	pcs.	1,673.68	#1	1,673.68	1,790.84
	Padding For Backrest	1	pcs.	242.43	#1	242.43	259.40
	Side Air Bag Unit	1	pcs.	1,450.33	#1	1,450.33	1,551.85
	RHS FRT SEAT AIRBAG	1	NEC	1,245.73	#1	1,245.73	1,332.93
	Air Bag Control Module	1	NEC	173.92	#1	173.92	186.09
	AIRBAG CONTROL UNIT	1	NEC	173.92	#1	173.92	186.09
	Drucksensor	1	NEC	173.92	#1	173.92	186.09
	RHS FRT DOOR AIRBAG SENSOR	1	NEC	173.92	#1	173.92	186.09
	Fender	1	NEC	629.40	#1	629.40	673.46
	RHF FENDER	1	NEC	629.40	#1	629.40	673.46
	Rivetted Cap Nut	4	NEC	2.50	#1	10.00	10.70

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/4

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Mr
LIM
TIONG GUAN
635A PUNGGOL DRIVE
#08-617
Singapore 821635

Document no.
Document date 06-09-2021
Customer no. 5211043801
Customer GST-ID
Dealer 30001
Job order number 2021033698/ 1
Job order date 04-09-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLB1020H	5G12BZ	28-03-2016	WWZZZAUZGW053450	Golf 1.2 TLBM 81 TSI D7F	44,013

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST	
5G4831056AS	Door RHF DOOR <i>DD</i>	1	pcs.	1,987.16	#1	1,987.16	2,126.26	993.58
5G4837652B	Door Seal <i>MC</i>	1	pcs.	107.32	#1	107.32	114.83	53.66
D 378500A2	Sound Absorber Laminated <i>MC</i>	1	pcs.	43.65	#1	43.65	46.71	21.83
5G4867912A	DOOR INSULATOR Door Seal Inner	1	pcs.	202.30	#1	202.30	216.46	101.15
N 91203801	RHF DOOR INNER SEAL <i>CRH</i>	2	pcs.	5.17	#1	10.34	11.06	5.17
8T0837947	Bolt With Polygon Socket <i>MC</i>	2	pcs.	1.45	#1	2.90	3.10	1.45
5K2837016J	nut <i>MC</i> Door Latch <i>MC</i> RHF DOOR LOCK	1	pcs.	399.55	#1	399.55	427.52	199.78
WHT005504	Fill. Hd. Screw <i>MC</i>	2	pcs.	2.76	#1	5.52	5.91	2.76
N 90581401	Plug <i>MC</i>	1	pcs.	0.57	#1	0.57	0.61	0.29
5N0837111 9B9	Cap Satin Black <i>MC</i>	1	pcs.	3.73	#1	3.73	3.99	1.87
WHT006515	Hex Socket Head Locating <i>MC</i>	1	pcs.	1.78	#1	1.78	1.90	0.89
5N0837885H	Bow <i>MC</i> SUPPORT DOOR HANDLE <i>MC</i>	1	pcs.	127.96	#1	127.96	136.92	
5G4837462H	Window Regulator Without <i>MC</i>	1	pcs.	426.71	#1	426.71	456.58	
5G0035453G	Woofers <i>MC</i> RHS FRT DOOR SPEAKER	1	pcs.	80.82	#1	80.82	86.48	
WHT005353	Pop-Rivet <i>MC</i>	8	pcs.	0.53	#1	4.24	4.54	2.12
3B0867334B	Grommet <i>MC</i>	3	pcs.	1.70	#1	5.10	5.46	2.55
WHT006587	Clip <i>MC</i>	3	pcs.	1.71	#1	5.13	5.49	2.57
5G4867024G BAM	Door Trim Panel <i>MC</i> RHF DOOR BOARD	1	pcs.	690.34	#1	690.34	738.66	
7L6868243	Clip <i>MC</i>	6	pcs.	1.63	#1	9.78	10.46	4.89
5G4809052	Side Panel <i>MC</i> RHS A-B PILLAR <i>MC</i>	1	pcs.	2,580.16	#1	2,580.16	2,760.77	
D 506KD1A4	2k-Füllschaum <i>MC</i>	1	pcs.	154.20	#1	154.20	164.99	
D 476KD1M2	Sealant Can Be Sprayed <i>MC</i>	1	pcs.	64.23	#1	64.23	68.73	
D 007500A2	Zinc Spray <i>MC</i>	1	pcs.	68.87	#1	68.87	73.69	
D 180003M2	2k-Body Adhesive <i>MC</i>	1	pcs.	444.39	#1	444.39	475.50	
D 314D36M2	Long-Life Underseal <i>MC</i>	1	pcs.	87.64	#1	87.64	93.77	
5G4809220	Pillar B Inner <i>MC</i> RHS B-PILLAR INNER PANEL (OUTER)	1	pcs.	1,187.53	#1	1,187.53	1,270.66	
5G4810070	Reinforcement For Pillar <i>MC</i> RHS B-PILLAR INNER PANEL (CTR)	1	pcs.	433.46	#1	433.46	463.80	
5G4809444	Pillar B Inner <i>MC</i> RHS B-PILLAR INNER PANEL (INNER)	1	pcs.	1,117.42	#1	1,117.42	1,195.64	
1K0010833P	Sticker <i>MC</i> STICKER (TYRE PRESSURE)	1	pcs.	15.84	#1	15.84	16.95	7.92
5G001000JB	Tire Pressure Label <i>MC</i>	1	pcs.	14.08	#1	14.08	15.07	7.04
7D0000279A	Identification Plate	1	pcs.	529.83	#1	529.83	566.92	264.92
5G4833056AD	STICKER (CHASSIS NO) Door <i>MC</i>	1	pcs.	2,147.19	#1	2,147.19	2,297.49	
5G6839700D	RHS REAR DOOR <i>MC</i> Door Seal Outer <i>MC</i>	1	pcs.	107.32	#1	107.32	114.83	53.66

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

3/4

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Mr
LIM
TIONG GUAN
635A PUNGGOL DRIVE
#08-617
Singapore 821635

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

06-09-2021
5211043801
30001
2021033698/ 1
04-09-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLB1020H	5G12BZ	28-03-2016	WVWZZZAUZGW053450	Golf 1.2 TLBM 81 TSI D7F	44,013

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 378500A2	Sound Absorber Laminated	1	pcs.	43.65	#1	43.65	46.71 21.83
8K0831402D	DOOR INSULATOR	1	pcs.	142.59	#1	142.59	152.57
8K0831402D	Door Hinge UPPER	1	pcs.	142.59	#1	142.59	152.57 71.30
8K0831402D	Door Hinge LOWER	1	pcs.	142.59	#1	142.59	152.57 71.30
N 91203801	Bolt With Polygon Socket	2	pcs.	5.17	#1	10.34	11.06 5.17
N 91205602	Hex Bolt With Internal To	4	pcs.	3.59	#1	14.36	15.37 7.18
8T0837947	nut	2	pcs.	1.45	#1	2.90	3.10 1.45
5G4839249A	Check Rod Door	1	pcs.	74.04	#1	74.04	79.22
5G6867914A	Door Seal Inner	1	pcs.	88.44	#1	88.44	94.63 44.22
5K4839016AF	Door Latch	1	pcs.	383.00	#1	383.00	409.81 191.50
WHT005504	DOOR LOCK	1	pcs.	383.00	#1	383.00	409.81 191.50
3C0837033C	Fill. Hd. Screw	2	pcs.	2.76	#1	5.52	5.91 2.76
1Y0837111	Locking Catch	1	pcs.	58.37	#1	58.37	62.46
5N0839885H	RH REAR DOOR LATCH	1	pcs.	5.11	#1	5.11	5.47 2.56
5G6839432J 5AP	Plug	1	pcs.	110.36	#1	110.36	118.09
5G4839462C	Bow	1	pcs.	110.36	#1	110.36	118.09
5G6867222G BAS	RHR DOOR HANDLE SUPPORT	1	pcs.	249.15	#1	249.15	266.59 124.58
7L6868243	Glass Channel Black	1	pcs.	249.15	#1	249.15	266.59 124.58
3AA868243A	RHR DOOR CHANNEL SEAL	1	pcs.	434.98	#1	434.98	465.43
5G0035453G	Window Regulator	1	pcs.	674.49	#1	674.49	721.70 337.25
WHT005353	Door Trim Panel	1	pcs.	674.49	#1	674.49	721.70 337.25
5G0810972D	RHR DOOR BOARD	1	pcs.	674.49	#1	674.49	721.70 337.25
5G0854858	Clip	6	pcs.	1.63	#1	9.78	10.46 4.89
5Q0501117A	Clip	1	pcs.	1.63	#1	1.74	1.74 0.82
WHT003853	Wooler	1	pcs.	80.82	#1	80.82	86.48 40.41
5Q0501049BH	RH REAR DOOR SPEAKER	1	pcs.	0.53	#1	4.24	4.54 2.12
N 10765901	Pop-Rivet	8	pcs.	0.53	#1	4.24	4.54 2.12
N 90648402	Wheelhouse Protector	1	pcs.	249.07	#1	249.07	266.50 124.54
N 10628601	RHS REAR FENDER LINER	1	pcs.	39.81	#1	39.81	42.60 19.91
VWLM3318	Side Member Trim	1	pcs.	39.81	#1	39.81	42.60 19.91
CINTURATO 205/55R16	RHR FENDER LINER LOWER TRIM	1	pcs.	39.81	#1	39.81	42.60 19.91
	Alloy Wheel Diamond Silve	1	pcs.	999.26	#1	999.26	1,069.21
	Rubber Valve	1	pcs.	3.60	#1	3.60	3.85
	Radlager Mit Montage Teil	1	pcs.	596.57	#1	596.57	638.33 298.29
	RHR WHEEL BEARING	1	pcs.	596.57	#1	596.57	638.33 298.29
	Stub Axle	1	pcs.	296.19	#1	296.19	316.92 148.10
	Bolt Hex. Hd.	4	pcs.	4.55	#1	18.20	19.47 9.10
	Rear Axle Beam	1	pcs.	2,602.74	#1	2,602.74	2,784.93 1,301.37
	Hexagon Flange Screw	2	pcs.	11.87	#1	23.74	25.40 11.87
	Bolt Hex. Hd.	8	pcs.	6.00	#1	48.00	51.36 24.00
	Bolt Hex. Hd. With Should	2	pcs.	8.15	#1	16.30	17.44 8.15
	DEGREASER CLEANER 500ml	1	pcs.	18.80	#1	18.80	20.12 9.40
	Pirelli CintuP7 205/55R16	1	pcs.	680.00	#1	680.00	727.60 544.00
	Towing assistance - AWP	1	pcs.	195.00	#1	195.00	208.65

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

4/4

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Mr
LIM
TIONG GUAN
635A PUNGGOL DRIVE
#08-617
Singapore 821635

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

06-09-2021
5211043801
30001
2021033698/ 1
04-09-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLB1020H	5G12BZ	28-03-2016	WVWZZZAUZGW053450	Golf 1.2 TLBM 81 TSI D7F	44,013

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	LABOUR	12	pcs.	840.00	#1	10,080.00	10,785.60
	SPRAY PAINT	8	pcs.	800.00	#1	6,400.00	6,848.00
	R&R FRT SEAT & CARPET	2	pcs. (photo)	840.00	#1	1,680.00	1,797.60
	R&R REAR LUGGAGE TRIM	2	pcs. (photo)	840.00	#1	1,680.00	1,797.60
	R&R REAR SEAT	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER DOOR MECHANISM	2	pcs.	840.00	#1	1,680.00	1,797.60
	VEHICLE ON BENCH - CELATTE	1	pcs.	1,500.00	#1	1,500.00	1,605.00
	R&R FRT SEAT AIRBAG	1	pcs.	360.00	#1	360.00	385.20
	R&R RHS FRT DOOR BOARD LEATHER	1	pcs.	360.00	#1	360.00	385.20
	R&R RHS REAR DOOR BOARD LEATHER	1	pcs.	360.00	#1	360.00	385.20
	FWD VS LONPAC						
	3RD PARTY VEHICLE SLW2745H						
	D.O.A: 01-09-2021						

840 X 10
800 X 5
SUPP (LABOUR): \$200.00

Quotation valid till 11-09-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	9,570.00	55,765.56	7%	4,573.49	65,335.56	69,909.05
Total	9,570.00	55,765.56		4,573.49	65,335.56	69,909.05

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: