



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0820
Vehicle No. : SLU9480K
Make & Model : HYUNDAI ELANTRA AD 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	400 500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	600
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
5	To remove and re-sealing of Off peak car licence plate.	120.00	100
6	To remove, replace and focus headlamp beam P- 3486-40 AI- 30 L- 1290 Supp- 30	60.00	30
Labour Total :		2300.00	1290
TOTAL (PARTS & LABOUR):		6480.40	

L/S- 3869.12
= 3850

Steve (LKK)
8/9/21, 1.00pm

N/L P/L
5 dgs
L/S
My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To remedy defect/damage/repairing
- To display damaged part(s) during recovery
- Parts prices are subject to market
- Third party survey is not a warranty/repayment
- No legal responsibility for the above
- Repairs/repairs/repairs are not a warranty/repayment
- Subject to terms & conditions of the insurance company

Wah Hong Motors & Credit Pte Ltd

Our Ref : WH0820							
Vehicle No. : SLU9480K						Page No. 3	
Make & Model : HYUNDAI ELANTRA AD 1.6							
QTY	DESCRIPTION (SUPPLEMENTARY)			CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>						
					-20%	0.00	
						0.00	
						0.00	
	<u>SPECIAL NETT ITEMS</u>						
1	Front Car Plate ✓ nec				30.00	✓	
	<u>LABOUR</u>						
Total Parts					30.00		