



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |   |   |                    |
|---|--|---|---|--------------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705 |  |   | Ref: CS/SMR21009403/Vuf3e2<br>Date: 01/11/2021<br>Code: SMR |                    |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |   |   |                    |
|   | Insured Veh.   | SHD 6275T   | Veh. Inspected  | SMN 1947J          |
|   | Policy No.   |   | Coverage (\$)   | 0.00               |
|   | Claim No.  | TAX/09/21/2003  | Excess (\$)   | 0.00               |
|   | Assign From  | HUA YEN   | Assign Date   | 07/09/2021         |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |   |                    |
|   | Make & Model   | HONDA VEZEL 1.5X  | c.c   | 1496               |
|   | Engine No.   | HIDDEN  | Year of Reg.  | 2019               |
|   | Chassis No.  | RU11314331  | Colour  | BLUE               |
|   | Odometer   | 65712 KM  | Steering  | IN ORDER           |
|   | Brakes   | IN ORDER  | Modification  | STANDARD ALLOY RIM |
|   | General  | GOOD  |   |                    |
| <b>3. Conditions of Tyres</b>   |  |   |   |                    |
|   |  | Size  | Make  | Balance            |
|   | R/H Front Tyre   | 215/60 R16  | ENASAVE   | 6 mm               |
|   | L/H Front Tyre   | 215/60 R16  | ENASAVE   | 6 mm               |
|   | R/H Rear Tyre  | 215/60 R16  | ENASAVE   | 6 mm               |
|   | L/H Rear Tyre  | 215/60 R16  | ENASAVE   | 6 mm               |
| <b>4. Description of Damages</b>  |  |   |   |                    |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |   |                    |
| <b>5. General Information</b>   |  |   |   |                    |
|   | Accident Date  | 03/09/2021  | Inspection Date   | 08/09/2021         |
|   | Survey held at   | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |   |                    |
| <b>5a. Remarks</b>  |  |   |   |                    |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |                    |
| <b>5b. Estimate Days of Repair</b>  |  |   |   |                    |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 10 Working Days   |                    |